RTR Services Inc.			RTR #: 5043826-01
GENERAL EQUIPMENT			ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:	2021		
MAKE:	Ditch-Witch	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	SK1550		
S/N:	DWPSK155VN00024	☐ NON-OPERATI	
POWER:	Yes	UNTESTABLE	
DESCRIPTION:	Ditch Witch Skid Steer	•	
SHOT / COUNT / HOUR: 579			
NOTES / COMMENTS: Right side track is off and needs to be put back on.			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
	ervices Inc.		RTR#:
	<b>EQUIPMENT</b>		ACCOUNT
CONDITI	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	
S/N:		☐ NON-OPERATI	
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
RTR Se	ervices Inc.		RTR #:
GENERAL	EQUIPMENT		ACCOUNT
CONDITI	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	L
S/N:		☐ NON-OPERATI	IONAL
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
7/21/25			
EMPLOYEE'S FULL NAME (PLEASE PRINT)  DATE  EMPLOYEE'S SIGNATURE			
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.			