	RTR	Services In	C.						RTR #: 505117				174-02	74-02		
BOX TRUCK										ACCOUNT NUMBER:						
CONDITION REPORT									ACCOUNT NAME:							
YEAR: 2016			MIL	MILES 195,411				VIN #:	1FDWE	3FS8GDC	37548					
MAKE: Ford			GV	W:	14,000 BOX H		IGHT	8'	BOX L	ENGTH 2	6'	BOX WII	отн	Gray		
N	IODEL:	E-350		wн	EELE	BASE:		C	DLOR:	EXTERIO	R: White	2	INTERIO	R:		
FI	NGINE:	6.8L V-10		HP				KEYS	· IGNITI	ON· 🖾 YI			t: ⊠ YES □ NO			
-	RANS:	Automatic			 FI·⊠	GAS □	DIESEI				☐ YES ⊠ !		RATING:			
		OTOR RUN?					DILISION I				NO TES (C)	.10	KATINO	•		
	DOE3 IVI	OTOR RUN?		ES		10 0		SICAL AF			NO					
			GD	FR	PR	N/A	COMMEN								PTIONS	
	FRONT	T BUMPER					COMMEN	13				⊠ P		TEERING		
		LIGHTS		$\boxtimes$									BRAK			
	HOOD TURN SIGNALS			$\boxtimes$										AIR		
	GRILLI				$\square$									∐ HYD WR L¢		
		NT FENDER			Ø		Dented						_ =		INDOWS	
ВОДУ	D DOO	R			$\boxtimes$		Dented						P	WR SI	EATS	
BO	D BOX			$\boxtimes$									🛛 🖂 P	WR M	IRRORS	
		BUMPER		]⊠	]								_ =		NDITIONER	
	l ·			$\boxtimes$											DE SEAT D/P DE SUSPENSION	_
		NT FENDER													RADIO	
		NT DOOR		$\boxtimes$									_	D / CE		DF -
	P BOX TOP			$\boxtimes$									_		ER SIZE? LUCENT ROOF	-
	D FRONT		H		H		% 75 <b>SIZ</b>	F•						_	CK LINING	
(0	D REAR A1 (S/D?)			$\boxtimes$			% 75 SIZ							OX DO	OME LIGHT	
	1			$\boxtimes$			% 75 SIZ						⊟ ⊔ s	IDE D	OOR	
TIRES	P FRONT		$\boxtimes$			% 75 SIZ						FUEL	TANK	S		
F	P REAR A1 (S/D?)		$\boxtimes$			% 75 <b>SIZ</b>							SINC	GLE GAL		
	P REA	R A2 (S/D?)		$\boxtimes$			% 75 SIZ	<b>E</b> :						] DUA	L GAL	
	SPARE						%	SIZE:						IUD FL	_APS	
ဟ	WINDS	NT DOOR		$\boxtimes$									WHEE	_	MINUM	
GLAS	REAR WINDOW													STE		
ฮ		NT DOOR		$\boxtimes$										BUD		
	MIRRO DASH	)RS		$\boxtimes$										SPO	KE ST S/D?	
~	DOOR PANELS			$\boxtimes$										ENSIO		
NTERIOR	SEAT(S)				$\boxtimes$		Driver Se	at Rippe	ed					AIR		
l H				$\boxtimes$										SPR		
Z	HEADL SLEEP			$\boxtimes$											M AXLE	
	BOX			$\boxtimes$									_ =		BRAKE	
	Evic	_	GD	FR	PR	UKN		DMMENT:						OOL E		
	ENGIN			] 🛚				neck eng	ıne ligh	on					AG AXLE	
ECHANICAL	CLUTC	SMISSION CH			$\boxtimes \Box$								_	RAMP IFTGA	TF	
Ž		RENTIALS		$\boxtimes$											A SYSTEM	
풍	BRAKES		$\boxtimes$													
ME	FRONT REAR			$\boxtimes$									$\dashv \exists$			
		RY/ELECTR					<b>5</b>						ᅱ旹			
	REFRIC	GERATION						.=	01	.== - = =	· · · · · · · · · · · · · · · · ·			B	D DECES:::::::::::::::::::::::::::::::::::	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																
	COMMENTS: Mileage Unverified. Unit will not drive. Said to be transmission issues															
		EMPLOYEE'S FUL	I NAME (D	LEASE	DDINIT	<u> </u>	_6/5/20	25 DATE			-	MDI OVEE'S	SIGNATURE			
		LIVIELO I EE 3 FUL	- IN~IVIE (P	ニレベシロ	L LYIN I	,		PAIL		EMPLOYEE'S SIGNATURE						

 All information conta	ined within this report is	deemed to be true and	accurate to the best	of my knowledge as of	the date listed above.	