RTR Services Inc.									RTR #: 5051174-04					
BOX TRUCK					415				ACCOUNT NUMBER:					
CONDITION REPORT									ACCOUNT NAME:					
	YEAR:	2016		MIL	_ES	133,871	VIN	VIN # : 8BNPF4CC9GE127725						
	MAKE:	Mercedes B	ercedes Benz		W:	14,000 BOX HEIG		IGHT 7'		BOX LENGTH	15' 6"	BOX WIDTH		
N	IODEL:	Sprinter		WH	IEELE	BASE: 170		COLO	OR: E	XTERIOR: W	hite	INTERIOR:	Gray/Black	
El	NGINE:	Mercedes 3	.0L	HP				KEYS: IC	EYS: IGNITION: X YES NO . DOOF		0 • DOOR:	R: ⊠ YES □ NO		
T	RANS:	Automatic		FU	EL: 🗆	GAS 🖂	DIESEL	DIESEL ANTIFREEZE TESTED: ☐ YES ☒ NO			⊠ NO	RATING:		
DOES MOTOR RUN? ☐ YES ☐ NO COLLISION DAMAGE? ☐ YES ☐ NO														
PHYSICAL APPEARANCE														
			GD	FR	PR	N/A	COMMENT	COMMENTS				OPTIONS		
	FRONT BUMPER HEADLIGHTS HOOD TURN SIGNALS GRILLE D FRONT FENDER			\boxtimes								☐ PWR S BRAKES	STEERING	
				\boxtimes										
				\boxtimes								HY		
				\boxtimes	믐							⊠ PWR L	OCKS VINDOWS	
ձ	D DOOR			\boxtimes								☐ PWR S		
ВОБУ	D BOX			\boxtimes								☐ PWR I	MIRRORS	
				\boxtimes								_ =	ONDITIONER DE SEAT D/P	
	_			\boxtimes									DE SUSPENSION	
	P FRONT FENDER			\boxtimes								☐ 🛛 AM FN	I RADIO	
				\boxtimes									B? PER SIZE?	
	TOP			\boxtimes	lΗ	ΙH							SLUCENT ROOF	
				\boxtimes			% 75 SIZE	:					CK LINING	
	D REAR A1 (S/D?)			\boxtimes			% 75 SIZE	:					OME LIGHT	
ပ္သ	D REAR A2 (S/D?)					\square	% 75 SIZE	:				⊠ SIDE □		
TIRES	P FRONT			\boxtimes			% 75 SIZE	:				FUEL TANK		
-	, ,						% 75 SIZE						GLE GAL	
	P REAR A2 (S/D?) SPARE						% 75 SIZE						AL GAL	
	WINDS						% S	SIZE:				⊠ MUD F WHEELS	LAPS	
SS	D FRONT DOOR			\boxtimes			Cracked						JMINUM	
GLAS	REAR WINDOW P FRONT DOOR MIRRORS			\boxtimes								☐ STE		
G				\boxtimes										
	DASH DOOR PANELS SEAT(S)			\boxtimes	H								JST S/D?	
~				\boxtimes								SUSPENSI	NC	
8							Dusty							
INTERIOR		FLOORING HEADLINER		\boxtimes										
=		SLEEPER		\boxtimes									EM AXLE	
	вох						N/A CC	MANTAITO.					E BRAKE	
	ENGINE		GD	FR 🖂	PR	UKN	N/A CC	MMENTS:				□ TOOL □ LIFT/T	AG AXLE	
٦ ۲		MISSION		\boxtimes								RAMP		
MECHANICAL	_	CLUTCH DIFFERENTIALS										X LIFTG	ATE RA SYSTEM	
¥	BRAKES											CAME	KA SISIEW	
EC	FRONT END			\boxtimes										
Σ	REAR			\boxtimes								니 뮤		
	REFRIC	RY/ELECTR GERATION		\boxtimes										
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE														
TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE COMMENTS: Mileage Unverified.														
		EMPLOYEE'S FUL	I NAME /P	OI EVE	PRINT	<u> </u>	6/5/20	25 DATE	_		EMDI OVEE'S	SIGNATURE		
		: : UL				,		· · · -			Lim LOILL 3	CIGITALOILE		

 All information conta	ined within this report is	deemed to be true and	accurate to the best	of my knowledge as of	the date listed above.	