

RTR Services Inc. BOX TRUCK CONDITION REPORT				RTR #: 5051174-05			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2021	MILES	85,407	VIN #:	7GZ67VC72MN006860		
MAKE:	GMC	GVW:	16,000	BOX HEIGHT	79" BOX LENGTH 19' BOX WIDTH		
MODEL:	Savana 4500	WHEELBASE:		COLOR: EXTERIOR:	White INTERIOR: Gray/Black		
ENGINE:	L8T 6.6L V8	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	Automatic	FUEL: ☒ GAS ☐ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO RATING:			
DOES MOTOR RUN?		☒ YES ☐ NO	COLLISION DAMAGE?		☐ YES ☒ NO		
PHYSICAL APPEARANCE							
BODY		GD	FR	PR	N/A	COMMENTS	OPTIONS
	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING
	HEADLIGHTS	☐	☒	☐	☐		BRAKES
	HOOD	☐	☒	☐	☐		☐ AIR
	TURN SIGNALS	☐	☒	☐	☐		☒ HYD
	GRILLE	☐	☒	☐	☐		☒ PWR LOCKS
	D FRONT FENDER	☐	☒	☐	☐		☐ PWR WINDOWS
	D DOOR	☐	☒	☐	☐		☐ PWR SEATS
	D BOX	☐	☒	☐	☐		☐ PWR MIRRORS
	REAR BUMPER	☐	☒	☐	☐		☒ AIR CONDITIONER
TAILLIGHTS	☐	☒	☐	☐		☐ AIR RIDE SEAT D/P	
REAR PANEL	☐	☒	☐	☐		☐ AIR RIDE SUSPENSION	
P FRONT FENDER	☐	☒	☐	☐		☒ AM FM RADIO	
P FRONT DOOR	☐	☒	☐	☐		☐ CD / CB? _____	
P BOX	☐	☒	☐	☐		☐ SLEEPER SIZE? _____	
TOP	☐	☒	☐	☐		☐ TRANSLUCENT ROOF	
TIRES	D FRONT	☐	☒	☐	☐	% 40 SIZE:	☐ E-TRACK LINING
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 40 SIZE:	☐ BOX DOME LIGHT
	D REAR A2 (S/D?)	☐	☒	☐	☐	% 40 SIZE:	☐ SIDE DOOR
	P FRONT	☐	☒	☐	☐	% 40 SIZE:	FUEL TANKS
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 40 SIZE:	☒ SINGLE GAL 32_
	P REAR A2 (S/D?)	☐	☒	☐	☐	% 40 SIZE:	☐ DUAL GAL _____
	SPARE	☐	☐	☐	☒	% SIZE:	☐ MUD FLAPS
GLASS	WINDSHIELD	☐	☐	☒	☐	Chipped	WHEELS
	D FRONT DOOR	☐	☒	☐	☐		☐ ALUMINUM
	REAR WINDOW	☐	☒	☐	☐		☐ STEEL
	P FRONT DOOR	☐	☒	☐	☐		☐ BUD
INTERIOR	MIRRORS	☐	☒	☐	☐		☐ SPOKE
	DASH	☐	☒	☐	☐		☐ EXHAUST S/D? _____
	DOOR PANELS	☐	☒	☐	☐		SUSPENSION
	SEAT(S)	☐	☒	☐	☐		☐ AIR
	FLOORING	☐	☒	☐	☐		☐ SPRING
MECHANICAL	HEADLINER	☐	☒	☐	☐		☐ PAD
	SLEEPER	☐	☒	☐	☐		☐ TANDEM AXLE
	BOX	☐	☒	☐	☐		☐ ENGINE BRAKE
		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
BRAKES	☐	☒	☐	☐	☐		
FRONT END	☐	☒	☐	☐	☐		
REAR END	☐	☒	☐	☐	☐		
BATTERY/ELECTR	☒	☐	☐	☐	☐	Replaced 7/2025	
REFRIGERATION	☐	☐	☐	☐	☒		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE COMMENTS: Mileage Unverified.							

EMPLOYEE'S FULL NAME (PLEASE PRINT)

 6/5/2025
DATE

EMPLOYEE'S SIGNATURE

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125

