RTR Services Inc. AUTO				_4			a	RTR #: 505 ACCOUNT NUMBER:				53606-01				
С		N REPOR	Г				0			COUNT						
YEAR: 2022		2022				KL8	CB6SA4	NC032285	032285			MILES: 77,832				
MAKE: Chevro		Chevrolet			COLO	R: EX	TERIOR:	Blue INTER			ERIOR:	Gray				
	MODEL:	Spark	Spark													
ENGINE: LV7					KEYS	: IGNIT	ION: 🛛	YES 🗌 NO	• DOOR:	⊠ YES □	] NO				_	
TRANS: Automatic							HYBRID					⊠ NO	RATING			
DOES MOTOR RUN?						COI		DAMAGE?		⊠ NO						
			GD	FR	PR	N/A	COMM		PEARANCE						OPTIONS	
	FRONT BUMPER			$\boxtimes$			CONIN	LINIO					PWR STEERING			
		HEADLIGHTS HOOD													BRAKES LOCKS	
	TURN SIGNALS			$\boxtimes$											WINDOWS	
	GRILLE D FRONT FENDER		무		+										SEATS MIRRORS	
	D FRONT DOOR			$\boxtimes$											ED GLASS	
вору	D REAR DOOR														SE CONTRO	L
B	D REAR FENDER REAR BUMPER														WHEEL HER SEATS	
	TAILLIGHTS			$\boxtimes$											GATION	
	TRUNK P FRONT FENDER		H												R CAMERA CONDITIONE	R
	P FRONT DOOR												╛	SUNF	ROOF	
	P REAR DOOR P REAR FENDER														M RADIO LAYER	
	TOP			$\boxtimes$		][]									OM WHEEL	S
TIRES	D FRONT						%	SIZE: 18 SIZE: 18						AWD	PACKAGE	
	D REAR P FRONT		$\mid \; \exists \; \mid$				%	SIZE: 18						-	ED SEATS	
F	P REAR SPARE			$\boxtimes$			%	SIZE: 18	5/55/15							
	WINDSHIELD						%	SIZE:								
တ္ဟ	D FRONT DOOR															
LAS	D REAR DOOR P FRONT DOOR															
9	P REAR DOOR			$\boxtimes$												
	REAR WINDOW DASH															
OR	DOOR PA	NELS		$\boxtimes$												
INTER	SEAT(S)															
Z	CARPET HEADLINER												10			
	ENGINE		GD	FR	PR	UKN	N/A	COMMEN	TS:					_		
;AL		TRANSMISSION														
MECHANICAL	CLUTCH BRAKES						$\boxtimes$									
CHA	FRONT E	ND														
ME	REAR END						D	7/0007								
BATTERY/ELECTR   🖂   🔲   🔲   Replaced 7/2025  THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO																
VAI	LIDATE / W	E RECOMME	END YO									-				
CO	MMENTS: I	Mileage Unve	erified.													
							6/13	/2025								
	EM	PLOYEE'S FULL				nin this repo	ort is deemed	DATE I to be true and	accurate to the b	est of my know		LOYEE'S SIG				-