RTR Services Inc.					RTR #: 505366								3				
PICKUP TRUCK				ACCOUNT NUMBER:													
			ACCOUNT NAME:														
YEAR: 2013				VIN #: 1FT7W2B1			EA78654		MILES:			118,731					
MAKE: Ford				COLO	R: EX	TERIOR:	R: White II		INTERIOR:	Та	ın						
MODEL: F-250		- Ot :			STYLE	Pickup Truck											
ENGINE: 6.7L V8 Power Stroke			ke	KEYS: IGNITION: ☑ YES ☐ NO • DOOR: ☑ YES ☐ NO													
TRANS: Automatic			FUEL: ☐ GAS ☐ DIESEL ☐ HYBRID ANTIFREEZE TESTED: ☐							YES 🛛	NO	RATING					
DOES MOTOR RUN?  ☐ YES			□ NO COLLISION DAMAGE? □ YES □ NO														
						PHYS	ICAL APP	EARANCE									
			G	FR	PR	N/A	COMMENTS						OPTIONS				
ВОВУ	FRONT BUMPER		D				Severe Collision Damage						⊠ P'	WR S	TEERING		
	HEADLIGHTS			$\boxtimes$			Covers Common Burnage						<ul> <li>✓ PWR BRAKES</li> <li>✓ PWR LOCKS</li> <li>✓ PWR WINDOWS</li> <li>✓ PWR SEATS</li> </ul>				
	HOOD			$\boxtimes$													
	TURN SIGNALS			$\boxtimes$			Course Callisian Remains										
	GRILLE DEPONT FENDER		<u> </u>	무			Severe Collision Damage										
	D FRONT FENDER D FRONT DOOR						Severe Collision Damage						=		GLASS		
	D REAR DOOR		$\parallel$										_		CONTRO	ı	
	D REAR FENDER		ΙĦ				Collision Damage							LT W		_	
	REAR BUMPER				$\boxtimes$		Collision Damage								ER SEATS		
	TAILLIGHTS			$\boxtimes$										IR CO	NDITIONE	R	
	TRUNK/BED			$\boxtimes$										<ul><li>☑ NAVIGATION</li><li>☐ REAR CAMERA</li></ul>			
	TAILGATE		<u> </u>				Collision Damage								CAMERA		
	P FRONT FENDER P FRONT DOOR						Severe Collision Damage  Passenger front door has been replaced							M/FM UNRO	RADIO		
	P REAR DOOR						Passenger front door has been replaced							D PLA			
	P REAR FENDER				$\boxtimes$									CUSTOM WHEELS			
	TOP			$\boxtimes$			Comolon Burnage							WD			
	D FRONT			$\boxtimes$			50 % SIZE: LT275/70R18								ACKAGE		
ES	D REAR			$\boxtimes$		][	50 % SIZE: LT275/70R18							<b>K4</b>			
TIRES	P FRONT P REAR						50 % SIZE: LT275/70R18 50 % SIZE: LT275/70R18						=	ED LII	NER RA SYSTEN	4	
-	SPARE		lΗ				% SIZE:							AIVIER	ASISIEN	1	
GLASS	WINDSHIELD		Ħ	$\boxtimes$			70 SIEE.										
	D FRONT DOOR			$\boxtimes$													
	D REAR DOOR			$\boxtimes$													
	P FRONT DOOR					]											
	P REAR DOOR REAR WINDOW			$\boxtimes$													
	DASH		╁┼		1 1												
OR	DOOR PANELS																
INTERIOR	SEAT(S)			$\boxtimes$													
E	CARPET			$\boxtimes$													
	HEADLIN	ER	G	FR	PR	UKN	N/A	A COMMENTS:									
			D					EIVI	J								
MECHANICAL	ENGINE	ISSION	$\parallel$				ᅡ										
	CLUTCH																
	BRAKES			$\boxtimes$													
H.	FRONT END		$\boxtimes$														
Ä	REAR END		_														
		//ELECTR						FOTION C	All V / Fire	OLONO NOT	<u> </u>	D::::-	-D D=-	DO::-	IDI E TO		
		MECHANICA E RECOMMEN							NLY / EMIS	SIUNS NOT V	EKIFIED	, BUYE	K KES	PUNS	IRLE LO		
СО	MMENTS: I	Mileage Unver	ified. I	Unit s	tarts ar	nd runs.	Unit canno	ot be drive	n, due to co	llision damag	je.						
		=								_							
							5/21/2	)F									
																-	
	EMPLO	YEE'S FULL NAME	(PLEAS	SE PRIN	IT)			DATE			EMPLOYE	EE'S SIGI	NATURE				
		All infor	rmation	contain	ed within	this report	is deemed to	be true and a	ccurate to the b	est of my knowled	dge as of th	e date lis	sted abov	e.		_	