

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b> 5054921	
		<b>ACCOUNT</b>	
		<b>ACCOUNT NAME:</b>	
<b>YEAR:</b>			
<b>MAKE:</b> Euro Vent	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
<b>MODEL:</b>	<input checked="" type="checkbox"/> OPERATIONAL		
<b>S/N:</b> n/a	<input type="checkbox"/> NON-OPERATIONAL		
<b>POWER:</b>	<input type="checkbox"/> UNTESTABLE		
<b>DESCRIPTION:</b>	(5) New Euro Vent Exhaust Hose & Reel		
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b>			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b> 5054921	
		<b>ACCOUNT</b> 1772516	
		<b>ACCOUNT NAME:</b> Off Lease Only LLC	
<b>YEAR:</b>			
<b>MAKE:</b> Venco	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
<b>MODEL:</b> rasf-10-5-81-00-01-01	<input type="checkbox"/> OPERATIONAL		
<b>S/N:</b> 20089104	<input type="checkbox"/> NON-OPERATIONAL		
<b>POWER:</b>	<input checked="" type="checkbox"/> UNTESTABLE		
<b>DESCRIPTION:</b>	Exhaust Fan Unit		
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b> Like New Condition			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b>	
		<b>ACCOUNT</b>	
		<b>ACCOUNT NAME:</b>	
<b>YEAR:</b>			
<b>MAKE:</b>	<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
<b>MODEL:</b>	<input type="checkbox"/> OPERATIONAL		
<b>S/N:</b>	<input type="checkbox"/> NON-OPERATIONAL		
<b>POWER:</b>	<input type="checkbox"/> UNTESTABLE		
<b>DESCRIPTION:</b>			
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b>			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

7/7/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125