RTR Services Inc.											RTR #: 506182					25-04		
BOX TRUCK											ACCOUNT NUMBER:							
CONDITION REPORT								01										
YEAR : 2019		2019		MII	LES	80,91	8			VIN #:	7GZ67VC	CG7KN01	.0190			,		
MAKE: GMC		GMC		GV	W:			BOX HE	IGHT	79"	BOX LEI	NGTH 1	6'	BOX WIDTH 96"		96"		
MODEL: Savana 4:		Savana 450	0	WH	IEELE	BASE:	ASE:		(COLOR:	EXTERIOR:	White	;	INTER	RIOR:	Gray		
ENGINE: GM		GM L96	L96							EYS: IGNITION: 🛛 YES 🗌 NO 🔹 DOOR			: 🗌 YES 🖾 NO					
T	RANS:	Automatic		FU	EL: 🗵	GAS	□ DI	ESEL	ANTIFREEZE TESTED: ☐ YES ☒ NO			O	RATING:					
	DOES M	OTOR RUN?		YES		ON	COL	LISION D				0						
								PHYS	SICAL A	APPEARA	NCE							
		GD	FR	PR	N/A	_	OMMENT	_						OPTIONS PWR STEERING				
ВОДУ	FRONT BUMPER							Driver side has a large dent, the passenger side has loose plastic				le has		PWR S	STEERING			
	HEADLIGHTS HOOD TURN SIGNALS						10	loose plastic						BR	BRAKES			
													☐ AIR					
													⊠ HYD ⊠ PWR LOCKS					
	GRILLE D FRONT FENDER				\Box	$\vdash \vdash$										UNDOWS		
	D DOO	R					Ι	Dented						$\exists \Box$	PWR S			
	D BOX															MIRRORS		
	REAR BUMPER TAILLIGHTS			\boxtimes										$\dashv \exists$		ONDITIONER DE SEAT D/P		
	REAR PANEL			\boxtimes											AIR RI	DE SUSPENSION		
	P FRONT FENDER P FRONT DOOR													$\dashv \exists$	AM FM	I RADIO		
	P BOX				╽╏									╛┦		PER SIZE?		
	TOP			\boxtimes												SLUCENT ROOF		
TIRES	D FRONT						_	670 SIZE						-		CK LINING OME LIGHT		
	D REAR A1 (S/D?) D REAR A2 (S/D?)						_	670 SIZE 670 SIZE						$\dashv \exists$	SIDE D			
	P FRONT						_	6 70 SIZE 6 70 SIZE							EL TANK			
	P REAR A1 (S/D?)							670 SIZE						-		GLE GAL		
	P REAR A2 (S/D?)						_	670 SIZE								AL GAL		
	SPARE						9/	% S	IZE:						MUD F	LAPS		
ဟ	WINDSHIELD D FRONT DOOR		$\mid \; \mid \; \mid \; \mid$	\boxtimes										_ wh	EELS	JMINUM		
ASS	i	WINDOW													⊠ STE			
ᄝ	P FRONT DOOR											□ BUD □ SPOKE						
	MIRRORS DASH				╁									\dashv		JST S/D?		
INTERIOR	DOOR PANELS														SPENSIO	ON		
	SEAT(S)							Ripped						_				
	FLOORING HEADLINER						L	Damaged						4	☐ SPF			
	SLEEPER													\dashv	_	EM AXLE		
	вох															E BRAKE		
MECHANICAL	ENGIN		GD 🗆	FR 🖂	PR	UKN			MMEN eck en	ıs: gine ligh	t on			\dashv \exists	TOOL LIFT/T	AG AXLE		
	TRANSMISSION			\boxtimes			- 1		CCK CII	igine ngi	it on			$\exists \overline{\Box}$	RAMP			
	CLUTCH							록							LIFTG			
	DIFFERENTIALS BRAKES							$\begin{array}{c c} \neg & AB \end{array}$	S ligh	t on					CAME	RA SYSTEM		
	FRONT END								ıs iigii	. 011								
	REAR END						[] [_									
	1	RY/ELECTR GERATION						╣						\dashv \Box				
	S IS NO	T A MECHANIC	CAL INS	SPECT	TION /	IT IS A	VIS	UAL INSP			DEF & DPF	FUNCTIO	NS NOT		D, BUY	ER RESPONSIBLE		
		TE / WE RECC S: Mileage Unv																
COMMENTS: Mileage Unverified. Passenger cargo door is locked with no key.																		