

RTR Services Inc. BOX TRUCK CONDITION REPORT				RTR #: 5061859-03			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2019	MILES	127,880	VIN #:	WDAPF4CD5KN035306		
MAKE:	Mercedes-Benz	GVW:	14,000	BOX HEIGHT	95" BOX LENGTH 15' BOX WIDTH 78.6"		
MODEL:	Sprinter	WHEELBASE:	170	COLOR: EXTERIOR:	White INTERIOR: Gray		
ENGINE:	Merc. 3.0L V6	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	Automatic	FUEL:	☐ GAS ☒ DIESEL	ANTIFREEZE TESTED: ☐ YES ☒ NO RATING:			
DOES MOTOR RUN?		☐ YES ☒ NO	COLLISION DAMAGE?		☐ YES ☒ NO		
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING BRAKES ☐ AIR ☒ HYD ☒ PWR LOCKS ☒ PWR WINDOWS ☒ PWR SEATS ☒ PWR MIRRORS ☒ AIR CONDITIONER ☐ AIR RIDE SEAT D/P _____ ☐ AIR RIDE SUSPENSION ☒ AM FM RADIO ☐ CD / CB? _____ ☐ SLEEPER SIZE? _____ ☐ TRANSLUCENT ROOF ☐ E-TRACK LINING ☒ BOX DOME LIGHT ☒ SIDE DOOR FUEL TANKS ☐ SINGLE GAL _____ ☐ DUAL GAL _____ ☒ MUD FLAPS WHEELS ☐ ALUMINUM ☐ STEEL ☐ BUD ☐ SPOKE ☐ EXHAUST S/D? _____ SUSPENSION ☐ AIR ☐ SPRING ☐ PAD ☐ TANDEM AXLE ☐ ENGINE BRAKE ☐ TOOL BOX _____ ☐ LIFT/TAG AXLE ☐ RAMP ☐ LIFTGATE ☒ CAMERA SYSTEM ☒ CRUISE CONTROL ☒ CARGO VAN ☒ SHELVEING
	HEADLIGHTS	☐	☒	☐	☐		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☐	☒	☐	Front passenger does not work	
	GRILLE	☐	☒	☐	☐		
	D FRONT FENDER	☐	☒	☐	☐		
	D DOOR	☐	☒	☐	☐		
	D BOX	☐	☒	☐	☐		
	REAR BUMPER	☐	☒	☐	☐		
	TAILLIGHTS	☐	☐	☒	☐	Large scratch near tailight	
REAR PANEL	☐	☒	☐	☐			
P FRONT FENDER	☐	☒	☐	☐			
P FRONT DOOR	☐	☒	☐	☐			
P BOX	☐	☒	☐	☐	Missing the key for the passenger cargo door.		
TOP	☐	☒	☐	☐			
TIRES	D FRONT	☐	☒	☐	☐	% 65 SIZE:	
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 65 SIZE:	
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:	
	P FRONT	☐	☒	☐	☐	% 65 SIZE:	
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 65 SIZE:	
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:	
	SPARE	☐	☐	☐	☒	% SIZE:	
GLASS	WINDSHIELD	☐	☒	☐	☐		
	D FRONT DOOR	☐	☒	☐	☐		
	REAR WINDOW	☐	☒	☐	☒		
	P FRONT DOOR	☐	☒	☐	☐		
	MIRRORS	☐	☒	☐	☐		
INTERIOR	DASH	☐	☒	☐	☐		
	DOOR PANELS	☐	☒	☐	☐		
	SEAT(S)	☐	☒	☐	☐		
	FLOORING	☐	☒	☐	☐		
	HEADLINER	☐	☒	☐	☐		
	SLEEPER BOX	☐	☒	☐	☒		
MECHANICAL		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	☐	☐	☒	☐	☐	Starts but will not run. Needs electrical repairs.
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	
	REFRIGERATION	☐	☐	☐	☐	☒	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE COMMENTS: Mileage Unverified.							

EMPLOYEE'S FULL NAME (PLEASE PRINT)

 6/23/2025
DATE

EMPLOYEE'S SIGNATURE

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125