	ртр (Sorvices Inc								RTR #: 506352						06.04				
RTR Services Inc. HEAVY TRUCK								.6-01												
CONDITION REPORT					Ū			ACCOUNT NAME:												
YEAR:		2021	021		.ES	516,693			VII	VIN #: 1XPBDP9X6MD749534				534						
MAKE:		Peterbilt		GV	W:	53,200	LICENS	E:			ST:		TAGS:	MON	TH		YR:			
MODEL:		579		WH	WHEELBASE:				COL	COLOR: EX			7		INTE			Grayf		
ENGINE:		Paccar MX-13					BODY TYPE:		Sleeper					N: XES			OOR:	∑ YES	S 🗌 NO	
		Automatic				GAS 🖂						ESTED: YES N		NO	RATI	NG:				
DOES MOTOR RUN? YES NO COLLISION DAMAGE? YES NO PHYSICAL APPEARANCE																				
			GD	FR	PR	N/A	СОММЕ			-AIVAI	NOL						OPI	TIONS		
ВОДУ	FRONT BUMPER																			
	HEAD LIGHTS HOOD			\boxtimes											BR	AKE:	S AIR			
	TURN SIGNALS			\boxtimes											▋_		HYD			
	GRILLE D FRONT FENDER			\boxtimes											$-\!\!\!\!/ \boxtimes$		/R LO	CKS NDOWS		
	D DOOR			\boxtimes													/R SE			
	D SLEEPER REAR BUMPER			\boxtimes	\Box										$-\mid \boxtimes $			RRORS DITION	ED	
	TAILLIGHTS			\boxtimes														SEAT		
	P FRONT FENDER			\boxtimes											$-\hspace{-0.1cm}\mid \boxtimes$			SUSPE		
	P FRONT DOOR			\boxtimes														5 TH WH		
	P SLEEPER TOP			\boxtimes													I FM R	ADIO D / CB?		
TIRES	D FRONT				\boxtimes		20 % 29	95/75F	R22.5 SI	IZE:					ᆸ			R SIZE?		
	D REAR A1 (S/D?)						20 % 295/75R22.5 SIZE:								ELECTRICAL PIGTAIL					
	D REAR A2 (S/D?) P FRONT				\boxtimes		20 % 295/75R22.5 SIZE: 20 % 295/75R22.5 SIZE:							⊠ FU		AD HA ANKS	_			
	P REAR A1 (S/D?)				\boxtimes		20 % 295/75R22.5 SIZE:								SINGLE GAL					
	P REAR A2 (S/D?) SPARE							20 % 295/75R22.5 SIZE: % SIZE:							\dashv_{\bowtie}	⊠ DUAL GAL ⊠ MUD FLAPS				
S	WINDSHIELD						1 crack	and 2	chips							IEEL				
LAS	D FRONT DOOR REAR WINDOW		님													=	ALUM STEE			
GL	P FRONT DOOR			\boxtimes													BUD			
	MIRRORS DASH		井	\boxtimes											\dashv_{\bowtie}		SPOK HAUS	.E T S/D? :	S	
RIOR	DOOR	OOR PANELS		\boxtimes												SPE	NSION		_	
SEAT				\boxtimes													AIR SPRIN	ıc		
INTER	CARPET HEADLINER		=														PAD	.0		
	SLEEPER		GD	⊠ FR	PR	UKN	N/A	COM	MENTS:									AXLE BRAKE		
MECHANICAL	ENGINE			\boxtimes							t does no	t op	erate.		╛	то	OL BO	ΟX		
	TRANSMISSION CLUTCH			\boxtimes											⊢믐		T/TAG T KIT	AXLE		
	DIFFERENTIALS		<u> </u>	\boxtimes											╛	***				
	BRAKES FRONT END			\boxtimes											$\dashv \exists$					
	REAR END				\parallel										ᅥᆸ					
TUI		BATTERY/ELECTR		DECT			ISLIAL IN	SDEC	TION OF	NI V /	DEE 9 DI) E E	LINCTI	ONE NOT	/EDIEI	ED B	IIVED	1		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																				
COMMENTS: Mileage Unverified. Missing the Battery cover steps on drivers side. Missing some of the exhaust system on the passenger side, including the covering steps. Engine warning light stating not to run the engine or more damage will occur. Starts and runs. The DEF system																				
was deleted and bypassed and will need to be replaced.																				
7/16/25 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE												_								
	'		•			•	oort is deeme			curate to	the best of r	ny kno		s of the date lis						