RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT				V		S	TICKNEW			RTR #: 506368 ACCOUNT ACCOUNT NAME:					2-01				
YEAR: 2023			BODY	TYPE:	Container			VIN #: 5JYMP2020PPC35059											
MAKE:		Dorsey			CAF	R CAPA													
MODEL:		MP20	P20		C	OLOR:	EXTERIOR: Silver												
LENGTH:		29'			WIDTH:		96"		I	HEIGHT:		3"			GVW: 60,500				
HITCH:					NTLE	🛛 5 ^{тн}	WHEEL PIN			BALL 🗌 2" BALL 🗌 2 5/16" B				5/16" BA	ALL				
CAN IT BE		TOWED? XES		S [COLLISI		ION DAMAGE?		🗆 YES 🛛 🗵		🛛 NO	KEYS:		Y	/ES		NO 🛛	
PHYSICAL APPEARANCE																			
			GD	FR	PR	N/A	COM	COMMENTS							OPTIONS				
MECHANICAL TIRES BODY	FRONT PANEL HITCH D SIDE PANEL D SIDE TIE DOWNS REAR PANEL P SIDE TIE DOWNS P SIDE TIE DOWNS P SIDE PANEL REAR BUMPER TOP RAMP(S) SIDE DOOR REAR DOOR D REAR A1 (S/D?) D REAR A2 (S/D?) P REAR A3 (S/D?) SIGNAL LIGHTS SIGNAL LIGHTS SIGNAL LIGHTS SIDER AXLES LANDING GEAR			××××××××××××××××××××××××××××××××××××××			% 50 % 50 % 50 % 50 % 50 % 50 % 7 % N/A □ □ □	R22.5						□ AIR RIDE SUSPENSION □ SPRING SUSPENSION □ SPRING SUSPENSION □ AIR BRAKES □ ELECTRICAL BRAKES □ HYD BRAKES □ SLIDER AXLE WHEELS □ □ SPOKE □ SPOKE □ STEEL □ ALUMINUM □ TOOL BOX □ MUD FLAPS □ DOVE TAIL □ TILT BED □ WHEDGE □ WINCH □ SPARE TIRE RACK □ REAR DOOR ☑ TANDEM AXLE □ SIDE DOOR □ LIFT/TAG AXLE □ ENCLOSED					
<u> </u>		NOT A MECHA		NSP	ECTIO	N / IT IS	A VISU	AL INSPE	CTION C	ONLY / WE	RE	COMMEN	DYC		ECT P	RIOR	TO P	URCHASE	
CO	MMENTS	3: Mileage unv	verified.																

EMPLOYEE'S FULL NAME (PLEASE PRINT)

7/1/25 DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125