RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT				4			INVINI			RTR ACCOUI NT NAM	NT	706			
YEAR: 2022		<i>/</i>		BODY TYPE:		Car Hauler		VIN #: 4B94A5327NB227003							
MAKE:		BCL Fabrication			CA	R CAPA	CITY 5-Car								
MODEL:		Coyote			COLOR:		EXTERIOR: Green								
LENGTH:		53'			WIDTH:		102"		HEIGHT:			GVW : 40,000			
HITCH: GOOS			ECK	☐ PI	PINTLE 🗵 5 TH \		WHEEL PIN		BALL 2" BALL 2 5/16" B			BALL			
С	AN IT BI	E TOWED?	⊠ YE	S I	□ NO	C	COLLISION DAMAGE?		⊠ YES	□ №	KEYS:	☐ YES	⊠ NO		
PHYSICAL APPEARANCE															
	FRONT PANEL		GD	FR ⊠					lantad				OPTIONS AIR RIDE SUSPENSION		
BODY	HITCH D SIDE PANEL D SIDE TIE DOWNS						Passenger front edge dented.					SPRING SPRING AIR BR CELECT HYD BI SLIDER WHEELS SPC SPC STE	SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE WHEELS BUD SPOKE STEEL ALUMINUM TOOL BOX		
TIRES	P REAR A3 (S/D?) SPARE						% 50 SIZE: Goodride 235/75R17.5 % 50 SIZE: Goodride 235/75R17.5 % SIZE: % 50 SIZE: Goodride 235/75R17.5 % 50 SIZE: Goodride 235/75R17.5 % SIZE: % SIZE:					MUD FLAPS LOADING RAMP BATTERY DOVE TAIL TILT BED WEDGE WINCH WINCH			
TAILLIGHTS SIGNAL LIGHTS CLEARANCE L SLIDER AXLES LANDING GEAI AIR HOSE/GLA ELECTRIC PIG		L LIGHTS RANCE LGT R AXLES NG GEAR DSE/GLAD		FR	PR		N/A COMMENTS:					SPARE TIRE RACK REAR DOOR TANDEM AXLE SIDE DOOR LIFT/TAG AXLE ENCLOSED			
	T. 110 10	NOT A MEQUA		INIOD	FOTIO	N / IT IO	A MOLIAL INORE	OTION O	NII V / M/E B		ND VOLUMO	L L	TO BURGUAGE		
							A VISUAL INSPE					PECT PRIOR	I O PURCHASE		
		EMPLOYEE'S FULI	L NAME (F	PLEASE	PRINT)		10/20/202 DATE	5			EMPLOYEE'S	SIGNATURE			