RTR Services Inc.										RTR #:	5073139-01					
SUV			اِ		0	ACCOUNT NUMBER:										
CONDITION REPORT				ACCOUNT NAME												
YEAR : 2016							2PF2GA305351			ı		MILE		158,187		
MAKE:		Land Rover		LIC	LICENSE:			ST:				TAGS: MN:			YR:	
MODEL:		Range Rover		СО	LOR:	EXTER	IOR: White INTERIOR:			Tan						
ENGINE:		V-6 3.0L		KE	KEYS: IGNITION			S □ NO ·	DOOR: [2	YES	□ NO					
TRANS:		Automatic		FUEL: GAS			☐ DIE	☐ DIESEL ☐ HYBRID ANTIFREEZE TEST			IFREEZE TEST	ED: YES	$\mathbf{S} \boxtimes$	NO	RATING	
DOES MOTOR RUN? ☑ YES					NO	COLL	ISION I	DAMAGE?	☐ YES	⊠ N	10					•
							Pŀ	IYSICAL AP	PEARAN	CE						
	GD			FR	PR	N/A		MENTS							OPTIONS	
	_	FRONT BUMPER HEADLIGHTS						Scratches							STEERIN	
	_	HOOD		\boxtimes				Scratches Scratches							BRAKES LOCKS	
	TURN SIGNALS							Coratorioc							WINDOW	'S
	GRILLE			\boxtimes									\boxtimes		THER SEA	TS
	D FRONT FENDER			\boxtimes									\boxtimes		SEATS	
ОБУ		D FRONT DOOR D REAR DOOR						Scratches							M RADIO	•
8	D REAR DOOR		\parallel		lΗ			Scratches Scratches							MIRRORS	
		REAR BUMPER		\boxtimes			WIIIIOI	Octatories							WHEEL	NOL .
	TAILLIGHTS		\boxtimes									\boxtimes	REAF	R DEFROS	ST	
	TAILGATE/R DOOR		\boxtimes											R WIPER		
	P FRONT FENDER		_	\boxtimes				Scratches Scratches							CONDITIO R AIR	NER
				\boxtimes		lΗ		Scratches							ROOF	
	TOP						Coratorioc							ED GLAS	3	
	D FRONT			\boxtimes				SIZE: 275/4							LAYER	
ES	D REAR			\boxtimes			% 30 SIZE: 275/402RR ☐ CUSTOM WHI						_	ELS		
TIRES	P FRONT	P FRONT P REAR		\boxtimes			% 30 SIZE: 275/402RR % 30 SIZE: 275/402RR; 21 PSI							4 X 4	PACKAG	_
ļ .	SPARE			lΗ	lΗ	% SIZE: 275/402RR, 21 FSI % SIZE: 275/402RR								RVIEW CA		
SS		WINDSHIELD		\boxtimes									\boxtimes	NAVI	GATION	
	D FRONT												\boxtimes		OW SEAT	
	D REAR DOOR D REAR PANEL			\boxtimes									\boxtimes		OW SEAT	
LAS	P FRONT DOOR			\boxtimes			Tint P	eeling							EKA STS TED SEAT	
ত	P REAR D						Tint Peeling						LED SEAT			
	P REAR P	P REAR PANEL		\boxtimes												
REAR WI		NDOW														
DASH DOOR PA SEAT(S) CARPET		NELS		\boxtimes			Scrate	rhes								
							Jorali	J.103					H			
Ë	CARPET		\boxtimes													
	HEADLINER			\boxtimes			NI/A									
	ENGINE	GD	FR 🖂	PR	UKN	N/A	COMMEN Check Er	ITS: ngine light	ton							
Ä	TRANSMISSION															
S	CLUTCH	CLUTCH					\boxtimes		-						-	
¥	BRAKES	BRAKES														
MECHANICAL	_	REAR END		\boxtimes												
Σ	BATTERY/ELECTR															
	IS IS NOT A	MECHANIC							ONLY / E	MISSIC	ONS NOT VERI	FIED, BUYE	RR	ESPO	NSIBLE T	0
		E RECOMM														
COMMENTS: Washer Fluid - low; Coolant level - low; Fuel level - low;																
							9/2	9/25								
	EMI	PLOYEE'S FULL						DATE				LOYEE'S SIGI				
			ul informatio	on conta	uned with	nn this repo	π is deeme	ed to be true and	accurate to the	ne best of	my knowledge as of	tne date listed	above	: .		