| RTR Se  | ervices Inc.          | RTR #: 5073141-04   |
|---|-----------------------|---|
| GENERAL EQUIPMENT   |                       | ACCOUNT   |
| CONDITI   | ON REPORT             | ACCOUNT NAME:   |
| YEAR:   | Unknown               |   |
| MAKE:   | Allmand               | ☐ YES ☑ NO  |
| MODEL:  | NLGR                  | ☐ OPERATIONAL   |
| S/N:  | 47-004065             | ⊠ NON-OPERATIONAL   |
| POWER:  | Diesel                | UNTESTABLE  |
| DESCRIPTION:  |                       |   |
| SHOT / COUNT / HOUR: Unknown  |                       |   |
| NOTES / COMMENTS: Dead  |                       |   |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE |                       |   |
|   |                       |   |
|   | ervices Inc.          | RTR #: 5073141-05   |
|   | _ EQUIPMENT           | ACCOUNT   |
|   | ON REPORT             | ACCOUNT NAME:   |
| YEAR:   |                       |   |
| MAKE:   |                       | ☐ YES ☑ NO ☐ EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL:  | <del>_</del>          | OPERATIONAL   |
| S/N:  |                       | □ NON-OPERATIONAL   |
| POWER:  | Diesel                | UNTESTABLE  |
| DESCRIPTION:  | Construction Light To |   |
| SHOT / COUNT / HOUR: 2,873 (Unverified)  NOTES / COMMENTS: Hours Unverified.  |                       |   |
|   |                       |   |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE |                       |   |
|   |                       |   |
| RTR Se  | ervices Inc.          | RTR #: 5073141-06   |
| GENERAL   | <b>EQUIPMENT</b>      | ACCOUNT   |
| CONDITI   | ON REPORT             | ACCOUNT NAME:   |
| YEAR:   | 2023                  |   |
| MAKE:   | Allmand               | ☐ YES ☑ NO  |
| MODEL:  | GR-Series Liquid      | □ OPERATIONAL   |
| S/N:  | 47-004071             | □ NON-OPERATIONAL   |
| POWER:  | Diesel                | UNTESTABLE  |
| DESCRIPTION:  | Construction Light To | wer   |
| SHOT / COUNT / HOUR: 5,177 (Unverified)   |                       |   |
| NOTES / COMMENTS: Hours Unverified.   |                       |   |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE |                       |   |
| 8/8/2025  |                       |   |
| EMPLOYEE'S FULL NAME (PLEASE PRINT)  DATE  EMPLOYEE'S SIGNATURE   |                       |   |
| All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.                                   |                       |   |
|   |                       |   |