RTR Services Inc.			RTR #: 5073141-16	
GENERAL EQUIPMENT		ACCOUNT		
CONDITION REPORT			ACCOUNT NAME:	
YEAR:	Unknown			
MAKE:	Allmand	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	NLGR		L .	
S/N:	47-004090	☐ NON-OPERATI	TIONAL	
POWER:	Diesel	UNTESTABLE		
DESCRIPTION:	RIPTION: Construction Light Tower			
SHOT / COUNT / HOUR: 3,897				
NOTES / COMMENTS: Hours unverified				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
RTR Se	ervices Inc.		RTR #: 5073141-17	
GENERAL	EQUIPMENT		ACCOUNT	
CONDITI	ON REPORT		ACCOUNT NAME:	
YEAR:	Unknown			
MAKE:	Allmand	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	NLGR		L .	
S/N:	47-004094	☐ NON-OPERATI	TIONAL	
POWER:	Diesel	UNTESTABLE		
DESCRIPTION:	Construction Light Tower			
SHOT / COUNT / HOUR: 3,962				
NOTES / COMMENTS: Hours unverified				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
RTR Se	ervices Inc.		RTR #: 5073141-18	
	GENERAL EQUIPMENT ACCOUNT			
	ON REPORT		ACCOUNT NAME:	
YEAR:	Unknown			
MAKE:	Allmand	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	NLGR		iL .	
S/N:	47-004058	☐ NON-OPERATI	TIONAL	
POWER:	Diesel	UNTESTABLE		
DESCRIPTION: Construction Light Tower. Tower rises but there are no lights.				
SHOT / COUNT / HOUR: 1,328				
NOTES / COMMENTS: Hours unverified.				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
8/8/2025				
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.				