RTR Services Inc. HEAVY TRUCK										RTR #: 508134						l5-01			
										ACCOUNT NUMBER:									
CONDITION REPORT										ACCOUNT NAME:									
YEAR:		2019		MII	LES	373,74	5			VIN #:	1XKY	D49X3	KJ293 ²	182					
MAKE:		Kenworth	Kenworth		GVW : 48,		LICENSE:				;	ST:		TAGS:	MON	тн 📗	YR:		
MODEL:		T680		WH	WHEELBASE:		230"		С	OLOR:	EXTER	RIOR:	Gree	n	INTE	RIOR:	Gray		
ENGINE:		Cummins		HP	HP 450 E		ODY TYPE: S		Sleep	oer	KE	YS: I	GNITIC	N: 🛛 YES	□ №	• DOC	R: XES	S 🗌 NO	
TRANS:		Automatic			EL: [☐ GAS 🗵	DIESEL	DIESEL AN			NTIFREEZE TESTED: ☐ YES ☒ NO					RATING:			
	DOES M	OTOR RUN?	⊠ YE	s [□ NC) с	OLLISION	N DAM	AGE?	? Y	'ES D	⊘NO							
										PPEARA	ANCE	_							
			GD	FR	PR	N/A	COMM	ENTS								O	PTIONS		
ВОДУ	FRONT BUMPER			\boxtimes			Dente	t									STEERING		
	HEAD I	LIGHTS		\boxtimes											BR	AKES ⊠ AIR	,		
	TURN SIGNALS GRILLE		H		\parallel														
				\boxtimes												PWR L	-		
	D FRONT FENDER			\boxtimes	$\ \ $		Paint i	s peeli	ing.							PWR V	VINDOWS		
	D DOOR D SLEEPER		H		ΙH	1									$-\mid \boxtimes \atop \boxtimes$		MIRRORS		
	REAR BUMPER														\square		ONDITION	ER	
	TAILLIGHTS REAR PANEL			\boxtimes	$\ \cdot\ $										$\square \square$		DE SEAT		
	P FRONT FENDER		╫		H	$+ \vdash$	Paint i	s peeli	ina.						$-\mid \boxtimes$. 5 TH WHEE		
	P FRONT DOOR			\boxtimes													IG 5 [™] WH	EEL	
	P SLEEPER			\boxtimes													I RADIO		
TIRES	TOP D FRONT		\dashv		H		50 % 2	295/75	R22.5	SIZE:					$-\mid \boxtimes $		/ CD / CB? PER SIZE?		
	D REAR A1 (S/D?)			\boxtimes			75 % 2	295/75	R22.5	SIZE:					\square	ELEC1	TRICAL PI		
	D REAR A2 (S/D?)			\boxtimes						SIZE:						GLAD EL TAN	HANDS		
	P FRONT P REAR A1 (S/D?)			\boxtimes						SIZE:					^۲ ۵		NS IGLE GAL		
	P REAR A2 (S/D?)			\boxtimes						SIZE:						□ DU	AL GAL 10		
	SPARE						D. d.	%	S	IZE:					🗵	MUD F	LAPS		
GLASS	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR			\boxtimes	$\ \ $		Rock	nips								IEELS ⊠ ALI	UMINUM		
						\boxtimes										☐ STE	EEL		
5				\boxtimes												☐ BUI			
	MIRRORS DASH		H		H	+ + =									\dashv	_	UST S/D?		
RIOR	DOOR PANELS SEAT(S) CARPET HEADLINER SLEEPER			\boxtimes											SU	SPENSI	ON		
I K				\boxtimes			Missin	g pass	senge	enger side seat. Wear and tear on driverside				е	⊠ AIR				
INTE				\square											☐ SPI				
			ō	1													EM AXLE		
	ENCIN	-	GD	FR	PR	UKN	N/A	COMI			h4/ NA = :	4	!a da		4 2		IE BRAKE		
MECHANICAL	ENGINE TRANSMISSION		H	\boxtimes				CHEC	ĸ ⊏Π <u>ξ</u>	Jille Lig	ht/ Main	Latice	ıs uue.		┦믐	TOOL LIFT/T	AG AXLE		
	CLUTC	Н					\square									WET K			
	DIFFERENTIALS			\boxtimes											_				
	BRAKES FRONT END			\boxtimes											\dashv				
	REAR END		\boxtimes																
TUI		RY/ELECTR		DECT		/ IT IS A 1		NSDEC	TION	I ONI V	/ DEE &	DDE E	HINCTI	ONS NOT	VEDIEI	ED BIIV	ED		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																			
COMMENTS: Mileage Unverified.																			
<u> </u>							8/2	0/25											
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE												_							
			All informa	ition cor	ntained	within this re	eport is deem	ed to be	true and	d accurate	to the best	of my kn	owledge a	as of the date li	sted above	e		_	