RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT				RTR #:	5083046-01
				ACCOUNT	
				ACCOUNT NAME:	

YEAR:	2024	BODY TYPE:	Flatbed	VIN #:	5E7HP2520RA003185
MAKE:	Kraftsman	CAR CAPACITY	N/A		
MODEL:	HP-40	COLOR:	EXTERIOR: Wood/ Black		
LENGTH:	20' + 5'	WIDTH:	102"	HEIGHT:	GVW: 49,000

HITCH: ☐ GOOSE NECK ☒ PINTLE ☐ 5TH WHEEL PIN ☐ 1 7/8" BALL ☐ 2" BALL ☐ 2 5/16" BALL

CAN IT BE TOWED?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO	KEYS:	☐ YES	☒ NO

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT PANEL	☐	☒	☐	☐	
	HITCH	☐	☒	☐	☐	
	D SIDE PANEL	☐	☐	☐	☒	
	D SIDE TIE DOWNS	☐	☒	☐	☐	
	REAR PANEL	☐	☐	☐	☒	
	P SIDE TIE DOWNS	☐	☒	☐	☐	Tool box damaged on passenger side.
	P SIDE PANEL	☐	☐	☐	☒	
	REAR BUMPER	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
	RAMP(S)	☐	☒	☐	☐	
	SIDE DOOR	☐	☐	☐	☒	
	REAR DOOR	☐	☐	☐	☒	
TIRES	D REAR A1 (S/D?)	☐	☒	☐	☐	% SIZE: 215/75/R17.5
	D REAR A2 (S/D?)	☐	☒	☐	☐	% SIZE: 215/75/R17.5
	D REAR A3 (S/D?)	☐	☐	☐	☒	% SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	% SIZE: 215/75/R17.5
	P REAR A2 (S/D?)	☐	☒	☐	☐	% SIZE: 215/75/R17.5
	P REAR A3 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	TAILLIGHTS	☐	☒	☐	☐	☐	
	SIGNAL LIGHTS	☐	☒	☐	☐	☐	
	CLEARANCE LGT	☐	☒	☐	☐	☐	
	SLIDER AXLES	☐	☒	☐	☐	☐	
	LANDING GEAR	☐	☒	☐	☐	☐	
	AIR HOSE/GLAD	☐	☒	☐	☐	☐	
	ELECTRIC PIGTAIL	☐	☒	☐	☐	☐	

OPTIONS

- ☒ AIR RIDE SUSPENSION
- ☐ SPRING SUSPENSION
- ☒ AIR BRAKES
- ☐ ELECTRICAL BRAKES
- ☐ HYD BRAKES
- ☐ SLIDER AXLE

WHEELS

- ☐ BUD
- ☐ SPOKE
- ☐ STEEL
- ☒ ALUMINUM

- ☒ TOOL BOX _____
- ☐ MUD FLAPS
- ☒ LOADING RAMP
- ☐ BATTERY
- ☐ DOVE TAIL
- ☐ TILT BED
- ☐ WEDGE
- ☐ WINCH
- ☐ SPARE TIRE RACK
- ☐ REAR DOOR
- ☒ TANDEM AXLE
- ☐ SIDE DOOR
- ☐ LIFT/TAG AXLE
- ☐ ENCLOSED

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS:

10/17/2025

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.