RTR Services Inc. DUMP TRUCK CONDITION REPORT		RTR #:	5093084-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2006	MILES	165,518	VIN #:	1HTWDAAR96J335863				
MAKE:	International	GVW:	41,000	BED HEIGHT	5' 5/8"	BED LENGTH	13' 1/2"	BED WIDTH	8'
MODEL:	7400	WHEELBASE:	15'	COLOR: EXTERIOR:	Blue	INTERIOR:	Gray		
ENGINE:	Navistar DT466	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:			
DOES MOTOR RUN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO				

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	Snow plow attached to unit
	HEADLIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D DUMP BED	☐	☒	☐	☐	
	REAR GATE	☐	☒	☐	☐	
	TAILLIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P DUMP BED	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	% 80 SIZE: 315/ 80R22.5
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 80/80 SIZE: 11R22.5
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☒	☐	☐	% 80 SIZE: 315/ 80R22.5
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 80/80 SIZE: 11R22.5
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☐	☒	☐	
	FLOORING	☐	☐	☒	☐	Dirty
	HEADLINER	☐	☒	☐	☐	
	DUMP BED	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☒ AIR RIDE SEAT D/P Both
- ☐ AIR RIDE SUSPENSION
- ☐ AM FM RADIO
- ☐ CD / CB? _____
- ☐ HITCH TYPE _____
- ☒ TARP SYSTEM
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☒ TOOL BOX _____
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☐ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☒ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S_
- SUSPENSION
  - ☐ AIR
  - ☒ SPRING
  - ☐ PAD
- ☐ LIFT/ TAG AXLE
- ☐ ARTICULATED
- ☒ BED CAPACITY _____
- ☐ WET KIT
- ☒ Tailgate Spreader
- ☐
- ☐
- ☐
- ☐
- ☐

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Fuses pop for unknown reason

	2/2/26	
EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125