

RTR Services Inc. HEAVY TRUCK CONDITION REPORT				RTR #: 5093328-01			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2021	MILES	345,945	VIN #:	3ALACXFE9MDMV9102		
MAKE:	Freightliner	GVW:	32,700 lbs	LICENSE:			
MODEL:	M2106	WHEELBASE:		COLOR: EXTERIOR:	Black		
ENGINE:	Cummins L9	HP		BODY TYPE:	Semi/Flatbed		
TRANS:	Automatic	FUEL:	☐ GAS ☒ DIESEL	ANTIFREEZE TESTED:	☐ YES ☒ NO		
DOES MOTOR RUN?		☒ YES ☐ NO		COLLISION DAMAGE?			
				☐ YES ☒ NO			
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING BRAKES ☒ AIR ☐ HYD ☒ PWR LOCKS ☒ PWR WINDOWS ☒ PWR SEATS ☒ PWR MIRRORS ☒ AIR CONDITIONER ☒ AIR RIDE SEAT D/P ☐ AIR RIDE SUSPENSION ☐ CONV. 5 TH WHEEL ☐ SLIDING 5 TH WHEEL ☐ AM FM RADIO ☒ TAPE / CD / CB? _____ ☐ SLEEPER SIZE? _____ ☐ ELECTRICAL PIGTAIL ☐ GLAD HANDS FUEL TANKS ☐ SINGLE GAL _____ ☒ DUAL GAL _____ ☒ MUD FLAPS WHEELS ☐ ALUMINUM ☐ STEEL ☐ BUD ☒ SPOKE ☐ EXHAUST S/D? _____ SUSPENSION ☒ AIR ☐ SPRING ☐ PAD ☐ TANDEM AXLE ☐ ENGINE BRAKE ☒ TOOL BOX ☐ LIFT/TAG AXLE ☐ WET KIT ☒ Goosneck Hitch ☐ Back up Camera Screen
	HEAD LIGHTS	☐	☒	☐	☐		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☒	☐	☐		
	GRILLE	☐	☒	☐	☐		
	D FRONT FENDER	☐	☒	☐	☐		
	D DOOR	☐	☒	☐	☐		
	D SLEEPER	☐	☒	☐	☐		
	REAR BUMPER	☐	☒	☐	☐		
	TAILLIGHTS	☐	☒	☐	☐		
TIRES	REAR PANEL	☐	☒	☐	☐		
	P FRONT FENDER	☐	☒	☐	☐		
	P FRONT DOOR	☐	☒	☐	☐		
	P SLEEPER	☐	☒	☐	☐		
	TOP	☐	☒	☐	☐		
	D FRONT	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
GLASS	D REAR A1 (S/D?)	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
	D REAR A2 (S/D?)	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
	P FRONT	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
	P REAR A1 (S/D?)	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
	P REAR A2 (S/D?)	☐	☒	☐	☐	80 % 295/75R22.5 SIZE:	
INTERIOR	SPARE	☐	☐	☐	☒	% SIZE:	
	WINDSHIELD	☐	☐	☒	☐	Cracked	
	D FRONT DOOR	☐	☒	☐	☐		
	REAR WINDOW	☐	☒	☐	☐		
	P FRONT DOOR	☐	☒	☐	☐		
MECHANICAL	MIRRORS	☐	☒	☐	☐		
	DASH	☐	☒	☐	☐		
	DOOR PANELS	☐	☒	☐	☐		
	SEAT(S)	☐	☒	☐	☐		
	CARPET	☐	☒	☐	☐		
MECHANICAL	HEADLINER	☐	☒	☐	☐		
	SLEEPER	☐	☒	☐	☒		
	ENGINE	☐	☒	☐	☐		
	TRANSMISSION	☐	☒	☐	☐		
	CLUTCH	☐	☐	☐	☒		
	DIFFERENTIALS	☐	☒	☐	☐		
	BRAKES	☐	☒	☐	☐		
	FRONT END	☐	☒	☐	☐		
MECHANICAL	REAR END	☐	☒	☐	☐		
	BATTERY/ELECTR	☒	☐	☐	☐	Replaced 10/2025	

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified.

10/15/2025

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125