

RTR Services Inc. BOX TRUCK CONDITION REPORT						RTR #: 5093616-01			
ACCOUNT NUMBER:			ACCOUNT NAME:						
YEAR:	2017	MILES	211,153		VIN #:	1HTMMMMM0HH520659			
MAKE:	International	GVW:	25,999	BOX HEIGHT		BOX LENGTH	26'	BOX WIDTH	8'6"
MODEL:	Durastar 4300	WHEELBASE:			COLOR:	EXTERIOR:	White	INTERIOR:	Black
ENGINE:	Cummins B6.7L	HP			KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO				
TRANS:	Automatic	FUEL:	☐ GAS ☒ DIESEL		ANTIFREEZE TESTED:		☐ YES ☒ NO		RATING:
DOES MOTOR RUN?		☒ YES ☐ NO		COLLISION DAMAGE?		☐ YES ☒ NO			
PHYSICAL APPEARANCE									
BODY	FRONT BUMPER	GD	FR	PR	N/A	COMMENTS		OPTIONS	
	HEADLIGHTS	☐	☒	☐	☐			☒ PWR STEERING	
	HOOD	☐	☒	☐	☐			BRAKES	
	TURN SIGNALS	☐	☒	☐	☐			☐ AIR	
	GRILLE	☐	☒	☐	☐			☒ HYD	
	D FRONT FENDER	☐	☒	☐	☐			☒ PWR LOCKS	
	D DOOR	☐	☒	☐	☐			☒ PWR WINDOWS	
	D BOX	☐	☒	☐	☐			☐ PWR SEATS	
	REAR BUMPER	☐	☒	☐	☐			☒ PWR MIRRORS	
	TAILLIGHTS	☐	☒	☐	☐			☒ AIR CONDITIONER	
REAR PANEL	☐	☒	☐	☐			☐ AIR RIDE SEAT D/P		
P FRONT FENDER	☐	☒	☐	☐			☐ AIR RIDE SUSPENSION		
P FRONT DOOR	☐	☒	☐	☐			☒ AM FM RADIO		
P BOX	☐	☒	☐	☐			☐ CD / CB?		
TOP	☐	☒	☐	☐			☐ SLEEPER SIZE?		
TIRES	D FRONT	☐	☒	☐	☐	%	SIZE:	☒ TRANSLUCENT ROOF	
	D REAR A1 (S/D?)	☐	☒	☐	☐	%	SIZE:	☒ E-TRACK LINING	
	D REAR A2 (S/D?)	☐	☒	☐	☐	%	SIZE:	☒ BOX DOME LIGHT	
	P FRONT	☐	☒	☐	☐	%	SIZE:	☐ SIDE DOOR	
	P REAR A1 (S/D?)	☐	☒	☐	☐	%	SIZE:	FUEL TANKS	
	P REAR A2 (S/D?)	☐	☒	☐	☐	%	SIZE:	☒ SINGLE GAL	
	SPARE	☐	☐	☐	☒	%	SIZE:	☐ DUAL GAL	
GLASS	WINDSHIELD	☐	☒	☐	☐			☒ MUD FLAPS	
	D FRONT DOOR	☐	☒	☐	☐			WHEELS	
	REAR WINDOW	☐	☒	☐	☒			☒ ALUMINUM	
	P FRONT DOOR	☐	☒	☐	☐			☐ STEEL	
	MIRRORS	☐	☒	☐	☐			☐ BUD	
INTERIOR	DASH	☐	☒	☐	☐			☐ SPOKE	
	DOOR PANELS	☐	☒	☐	☐			☐ EXHAUST S/D?	
	SEAT(S)	☐	☒	☐	☐			SUSPENSION	
	FLOORING	☐	☒	☐	☐			☐ AIR	
	HEADLINER	☐	☒	☐	☐			☒ SPRING	
	SLEEPER	☐	☐	☐	☒			☐ PAD	
MECHANICAL	BOX	☐	☒	☐	☐			☐ TANDEM AXLE	
	ENGINE	☐	☒	☐	☐			☐ ENGINE BRAKE	
	TRANSMISSION	☐	☒	☐	☐			☐ TOOL BOX	
	CLUTCH	☐	☒	☐	☐			☐ LIFT/TAG AXLE	
	DIFFERENTIALS	☐	☒	☐	☐			☒ RAMP	
	BRAKES	☐	☒	☐	☐			☒ LIFTGATE	
	FRONT END	☐	☒	☐	☐			☐ CAMERA SYSTEM	
	REAR END	☐	☒	☐	☐				
	BATTERY/ELECTR	☐	☐	☒	☐	Needs battery replaced.			
REFRIGERATION	☐	☐	☐	☐					
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE									
COMMENTS: Mileage Unverified.									