DTD C	anticoo Inc		RTR #: 5093729-01
RTR Services Inc. GENERAL EQUIPMENT		ACCOUNT	
CONDITION REPORT			ACCOUNT NAME:
YEAR:	2023		ACCOUNT NAME.
MAKE:	Rayco	⊠ YES □ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	RG165T-R	☐ OPERATIONAL	
S/N:	RG165T-R0060223	☐ NON-OPERATI	
POWER:	Yes	UNTESTABLE	
DESCRIPTION:	2023 Rayco RG165T-R		<u>-</u>
SHOT / COUNT / HOUR: 548			
NOTES / COMMENTS: Teeth are at 50%			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO			
VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
RTR Se	ervices Inc.		RTR #:
GENERAL	EQUIPMENT		ACCOUNT
CONDITI	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	NL
S/N:		☐ NON-OPERATI	FIONAL
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / F	HOUR:		
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
RTR Se	ervices Inc.		RTR #:
	EQUIPMENT		ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	NL .
S/N:		☐ NON-OPERATI	TIONAL
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
9/23/25			
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.			
<u></u>	All information contain	eu wittiiti this report is deer	arried to be true and accurate to the best of my knowledge as of the date listed above.