

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #: 5093995			
				ACCOUNT NUMBER:			
				ACCOUNT NAME:			
YEAR:	2000	VIN/SN:	1VRT11241Y1000174				
MAKE:	Vermeer	☒ WHEEL ☐ TRACK ☐ STATIONARY ☐ SKIDMOUNTED					
MODEL:	V120	COLOR:	EXTERIOR:	Yellow	INTERIOR:		
ENGINE:	Cummins 4BTA 3.9 Turbo diesel	HP:	90	KEYS: IGNITION: ☐ YES ☒ NO ☐ N/A • DOOR: ☐ YES ☒ NO ☐ N/A			
TRANS:	Hyd	FUEL: ☒ DIESEL ☐ GAS ☐ PROPANE ☐ CNG ☐ ELECTRIC ☐ HYDRAULIC					
HRS:	Unknown	DOES IT RUN?		☐ YES ☒ NO ☐ UNK			
		LENGTH:		WIDTH:			
				HEIGHT:			
				WEIGHT:			
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	
BODY	FRONT	☐	☒	☐	☐		
	HEAD LIGHTS	☐	☐	☐	☒		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☐	☐	☒		
	GRILLE	☐	☐	☐	☒		
	L FRONT FENDER	☐	☐	☐	☒		
	L DOOR	☐	☐	☐	☒		
	L REAR PANEL	☐	☒	☐	☐		
	SAFETY LIGHTS	☐	☐	☐	☒		
	REAR	☐	☒	☐	☐		
	TAIL LIGHTS	☐	☐	☐	☒		
	FRAME	☐	☒	☐	☐		
	TURN SIGNALS	☐	☐	☐	☒		
	R FRONT FENDER	☐	☐	☐	☒		
	R FRONT DOOR	☐	☐	☐	☒		
	R REAR PANEL	☐	☒	☐	☐		
WORK LIGHTS	☐	☐	☐	☒			
TOP	☐	☒	☐	☐			
TIRES	L FRONT	☐	☐	☒	☐	20 % 38X18-20 SIZE:	
	L REAR	☐	☐	☒	☐	20 % 38X18-20 SIZE:	
	R FRONT	☐	☐	☒	☐	20 % 38X18-20 SIZE:	
	R REAR	☐	☐	☒	☐	20 % 38X18-20 SIZE:	
GLASS	WINDSHIELD	☐	☐	☐	☒		
	L DOOR	☐	☐	☐	☒		
	REAR WINDOW	☐	☐	☐	☒		
	R DOOR	☐	☐	☐	☒		
	MIRRORS	☐	☐	☐	☒		
INTERIOR	DASH/GAUGES	☐	☒	☐	☐		
	DOOR PANELS	☐	☐	☐	☒		
	SEAT	☐	☒	☐	☐		
	CARPET/MAT	☐	☒	☐	☐		
	CONTROLS	☐	☒	☐	☐		
		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	Missing Hydraulic pump, fuel / Water pump motor, turbo, and Air intake components.
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	DIFFERENTIAL	☐	☐	☐	☒	☐	
	2 ND DIFFERENTIAL	☐	☐	☐	☒	☐	
	UNDERCARRIAGE	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☒	☐	Center hub of cutting wheel is cracked.
REAR END	☐	☐	☐	☒	☐	Rear steer cylinders have been replaced with ratchet binders.	
BATTERY/ELECTR	☐	☐	☐	☒	☐		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE							
COMMENTS: Hours unverified.							