

RTR Services Inc. BUS CONDITION REPORT				RTR #: 5101004-01			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2016	MILES	272,644	VIN #:	WKKA40XH8G3050117		
MAKE:	Setra	GVW	50530	SEATS: ☐ LEATHER ☒ CLOTH			
MODEL:	S 407 CC	WHEELBASE:	289	COLOR: EXTERIOR:	Blue		
ENGINE:	L6, 12.8L; Turbo	HP	410	BODY TYPE:	Bus		
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL	ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:		
DOES MOTOR RUN?		☒ YES ☐ NO	COLLISION DAMAGE?		☐ YES ☒ NO		
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING BRAKES ☒ AIR ☐ HYD ☒ PWR LOCKS ☐ PWR WINDOWS ☐ PWR SEATS ☒ PWR MIRRORS ☒ AIR CONDITIONER ☒ AIR RIDE SEAT ☐ AIR RIDE SUSPENSION ☐ PWR MIRRORS ☐ ENGINE BRAKE ☒ AM FM RADIO ☒ CD / CB? _____ ☐ FIRE EXTINGUISHER ☐ FIRST AID KIT ☐ BACKUP CAMERA FUEL TANKS ☒ SINGLE GAL _____ ☐ DUAL GAL _____ ☒ MUD FLAPS WHEELS ☒ ALUMINUM ☐ STEEL ☐ BUD ☐ SPOKE ☐ TANDEM AXLE SUSPENSION ☒ AIR ☐ SPRING ☐ PAD ☒ PASSENGERS _____ ☒ VIDEO SYSTEM ☐ OVERHEAD BINS ☐ REAR LUGGAGE ☐ BEDS _____ ☒ LAVATORY ☒ 120 VOLT OUTLETS ☒ VIDEO SYSTEM ☐ REFRIGERATOR ☐ TOOL BOX ☐ CAMERA SYSTEM
	HEADLIGHTS	☐	☒	☐	☐		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☒	☐	☐		
	GRILLE	☐	☐	☐	☒		
	D FRONT FENDER	☐	☒	☐	☐		
	D DOOR	☐	☒	☐	☐		
	D SIDE PANEL	☐	☒	☐	☐		
	REAR BUMPER	☐	☒	☐	☐		
	TAILLIGHTS	☐	☒	☐	☐		
REAR PANEL	☐	☒	☐	☐			
P FRONT FENDER	☐	☒	☐	☐			
P FRONT DOOR	☐	☒	☐	☐			
P SIDE PANEL	☐	☒	☐	☐			
TOP	☐	☒	☐	☐			
TIRES	D FRONT	☐	☒	☐	☐	% 30 SIZE: 315/80R 22.5	
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 30 SIZE: 315/80R 22.5	
	D REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R 22.5	
	P FRONT	☐	☒	☐	☐	% 50 SIZE: 315/80R 22.5	
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R 22.5	
	P REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R 22.5	
	SPARE	☐	☐	☐	☒	% SIZE: 315/80R 22.5	
GLASS	WINDSHIELD	☐	☒	☐	☐		
	D SIDE	☐	☒	☐	☐		
	REAR WINDOW	☐	☐	☐	☒		
	P SIDE	☐	☒	☐	☐		
MIRRORS	MIRRORS	☐	☒	☐	☐		
	DASH	☐	☒	☐	☐		
	HEADLINER	☐	☒	☐	☐		
	FLOORING	☐	☒	☐	☐		
	DRIVER SEAT	☐	☒	☐	☐		
INTERIOR	PASSENGER SEATS	☐	☒	☐	☐		
	LAVATORY	☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
MECHANICAL		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELEC	☐	☒	☐	☐	☐	

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE
 COMMENTS: Mileage Unverified.

Jason Berry

11/06/2025

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125