

RTR Services Inc. HEAVY TRUCK CONDITION REPORT				RTR #: 5101006-01			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2019	MILES	451,280	VIN #:	3AKJHHDV3KSJW8912		
MAKE:	Freightliner	GVW:	52,000	LICENSE:			
MODEL:	Cascadia	WHEELBASE:		COLOR: EXTERIOR:	Tan		
ENGINE:	Detroit DD13 12.8 L	HP		BODY TYPE:	Sleeper		
TRANS:	Automatic	FUEL:	☐ GAS ☒ DIESEL	ANTIFREEZE TESTED:	☐ YES ☒ NO		
DOES MOTOR RUN?		☒ YES	☐ NO	COLLISION DAMAGE?			
				☐ YES ☒ NO			
PHYSICAL APPEARANCE							
BODY		GD	FR	PR	N/A	COMMENTS	OPTIONS
	FRONT BUMPER	☐	☐	☒	☐	Passenger side loose	☒ PWR STEERING
	HEAD LIGHTS	☐	☒	☐	☐		BRAKES
	HOOD	☐	☒	☐	☐		☐ AIR
	TURN SIGNALS	☐	☒	☐	☐		☐ HYD
	GRILLE	☐	☒	☐	☐		☒ PWR LOCKS
	D FRONT FENDER	☐	☒	☐	☐		☒ PWR WINDOWS
	D DOOR	☐	☒	☐	☐		☒ PWR SEATS
	D SLEEPER	☐	☒	☐	☐		☐ PWR MIRRORS
	REAR BUMPER	☐	☐	☐	☒		☒ AIR CONDITIONER
TIRES	TAILLIGHTS	☐	☒	☐	☐		☐ AIR RIDE SEAT D/P
	REAR PANEL	☐	☒	☐	☐		☐ AIR RIDE SUSPENSION
	P FRONT FENDER	☐	☒	☐	☐		☐ CONV. 5 TH WHEEL
	P FRONT DOOR	☐	☒	☐	☐		☒ SLIDING 5 TH WHEEL
	P SLEEPER	☐	☒	☐	☐		☒ AM FM RADIO
	TOP	☐	☒	☐	☐		☐ TAPE / CD / CB? _____
GLASS	D FRONT	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	☐ SLEEPER SIZE? _____
	D REAR A1 (S/D?)	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	☐ ELECTRICAL PIGTAIL
	D REAR A2 (S/D?)	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	☐ GLAD HANDS
	P FRONT	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	FUEL TANKS
	P REAR A1 (S/D?)	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	☐ SINGLE GAL _____
INTERIOR	P REAR A2 (S/D?)	☐	☒	☐	☐	50 % 295/75R22.5 SIZE:	☐ DUAL GAL _____
	SPARE	☐	☐	☐	☒	% SIZE:	☒ MUD FLAPS
	WINDSHIELD	☐	☒	☐	☐		WHEELS
	D FRONT DOOR	☐	☒	☐	☐		☒ ALUMINUM
	REAR WINDOW	☐	☐	☐	☒		☐ STEEL
MECHANICAL	P FRONT DOOR	☐	☒	☐	☐		☐ BUD
	MIRRORS	☐	☒	☐	☐		☐ SPOKE
	DASH	☐	☒	☐	☐	Multiple Warning Lights.	☐ EXHAUST S/D? _____
	DOOR PANELS	☐	☒	☐	☐		SUSPENSION
	SEAT(S)	☐	☒	☐	☐		☐ AIR
MECHANICAL	CARPET	☐	☒	☐	☐		☐ SPRING
	HEADLINER	☐	☒	☐	☐		☐ PAD
	SLEEPER	☐	☒	☐	☐		☒ TANDEM AXLE
		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	☐	☐	☐	☒	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	DIFFERENTIALS	☐	☐	☐	☒	☐	
BRAKES	☐	☐	☐	☒	☐		
FRONT END	☐	☐	☐	☒	☐		
REAR END	☐	☐	☐	☒	☐		
BATTERY/ELECTR	☐	☐	☐	☒	☐		

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Passenger side steps are damaged. Errors on dash: Active Break Assist Not Available. Water in Fuel. MIL On.

10/16/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125