	RTR (	Services Inc	•								RTR #: 510189						A_03			
HEAVY TRUCK											ACCOUNT NUMBER:						<del>1-03</del>			
CONDITION REPORT											ACCOUNT NAME:									
YEAR:		2017	MII	LES	921,383	•	\	VIN #: 3AKGGLDR8HSGC5823					1							
MAKE:		Freightliner		_	<b>GVW</b> : 52,000		L	LICENSE:				ST:	1	TAGS:	MON			YR:		
MODEL:		Cascadia		HP	_	BASE:	230		LOR:			White	~	INTE				n/Gray		
ENGINE:		Detroit DD15 14.8L					ODY TYPE: Sle							N: YES				: M YES	I NO	
	RANS:	Automatic													RAT	ING				
DOES MOTOR RUN?   ☑ YES   ☐ NO   COLLISION DAMAGE?   ☐ YES   ☑ NO  PHYSICAL APPEARANCE																				
				FR	PR	N/A	COMM								OPTIONS					
ВОДУ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS						Loose	Loose/Partially Detatched												
				$\boxtimes$									Ві		LS ☑ AIR					
				$\boxtimes$													HYD	-1/-		
	GRILLE D FRONT FENDER						Loose								<ul><li>□ PWR LOCKS</li><li>⊠ PWR WINDOWS</li></ul>					
	D DOO		$\boxtimes$												] P	WR SE	ATS			
	D SLEE					Dente	1									WR MIF	RRORS IDITIONI	=D		
	TAILLIGHTS			$\boxtimes$			Dente	4								Α	IR RIDE	SEAT I	D/P	
	REAR PANEL P FRONT FENDER						Cracke	- d										E SUSPE		
	P FRONT DOOR						Cracke	ŧu							$\dashv  \models$			5 <sup>TH</sup> WH		
	P SLEE		$\boxtimes$													M FM R				
TIRES	TOP D FROM					30 % 2	30 % 295/75R22.5 SIZE:								] I ] S		D / CB? R SIZE?			
	D REAR A1 (S/D?)				$\boxtimes$		10 % 295/75R22.5 SIZE:									ELECTRICAL PIGTAIL				
	D REAR A2 (S/D?) P FRONT			$\boxtimes$			50 % 295/75R22.5 SIZE: 10 % 295/75R22.5 SIZE:								🗵		LAD HA TANKS	_		
	P REAR A1 (S/D?)				$\boxtimes$		10 % 295/75R22.5 SIZE:								<b></b>	SINGLE GAL				
	P REAR A2 (S/D?) SPARE			$\boxtimes \Box$			50 % 2	295/75F %							$\dashv_{\scriptscriptstyle{ ho}}$	☑ DUAL GAL <u>80</u> ☑ MUD FLAPS				
	WINDSHIELD						% SIZE:								☑ MUD FLAPS WHEELS					
SS	D FRONT DOOR			$\boxtimes$												_	ALUM	_		
GLAS	REAR WINDOW P FRONT DOOR											_	☑ STEEI ☐ BUD	L						
	MIRRORS			$\boxtimes$													SPOK		_	
~	DASH DOOR PANELS						Scratc	Scratched								☐ ☑ EXHAUST S/D? <u>S</u> SUSPENSION				
₩   SEAT(							Worn							AIR						
NTE	CARPET HEADLINER						Worn										SPRIN	NG		
=	SLEEP		$\boxtimes \Box$			Doors missing								☐ PAD ☑ TANDEM AXLE						
	ENCINE		GD	FR	PR	UKN	N/A	COM	/ENTS	<b>3</b> :						: _		BRAKE		
MECHANICAL	ENGINE TRANSMISSION			$\boxtimes$											<b>                                    </b>	:	OOL BO			
	CLUTC	Н					$\boxtimes$									) <b>v</b>	VET KIT			
	DIFFERENTIALS BRAKES			$\boxtimes$				Worn	Down											
	FRONT END							******	<b></b>											
_	REAR END			$\boxtimes$	$\ \cdot\ $										_	] 1				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER																				
RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE  COMMENTS: Mileage Unverified.																				
							10/	27/20	25											
		EMPLOYEE'S FULL	NAME (F	LEASE	PRINT	·)	10/	DAT		<del></del>			1	EMPLOYEE'S	S SIGNAT	TURE			_	
						•	ort is deem	ed to be t	rue and a	accurate t	to the bes	t of my kn	owledge a	s of the date	isted abo	ve.				