

YEAR: 2022	MILES: 158,617	VIN #: 3C7WRNDL9NG264003
MAKE: Ram	GVW: 19,500	BED WIDTH: 101"
MODEL: 5500	WHEELBASE: 168.5	BED LENGTH: 241"
ENGINE: Cummins 6.7	HP: 360	BODY TYPE: Rollback
TRANS: AS69RC Automatic	FUEL: <input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
DOES MOTOR RUN? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	COLLISION DAMAGE? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	RATING:

PHYSICAL APPEARANCE

	GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damage to the right side	<input checked="" type="checkbox"/> PWR STEERING
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damage to the right side	<input type="checkbox"/> AIR
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> HYD
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR LOCKS
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damaged	<input checked="" type="checkbox"/> PWR WINDOWS
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR SEATS
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR MIRRORS
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> AIR CONDITIONER
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Damage to Passenger side box	<input type="checkbox"/> AIR RIDE SEAT D/P _____
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> AIR RIDE SUSPENSION
TIRES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 225/70/19.5	<input checked="" type="checkbox"/> AM FM RADIO
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 225/70/19.5	<input type="checkbox"/> CD / CB? _____
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> HITCH TYPE _____
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 225/70/19.5 (3 broken studs)	<input type="checkbox"/> LIFT/TAG AXLE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 225/70/19.5 (Out side tire is low)	<input type="checkbox"/> TANDEM AXLE
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> ENGINE BRAKE
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input checked="" type="checkbox"/> TOOL BOX 2
GLASS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> FUEL TANKS
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damage where the door meets the fender	<input checked="" type="checkbox"/> SINGLE GAL _____
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> DUAL GAL _____
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> MUD FLAPS
INTERIOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> WHEELS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> ALUMINUM
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Stained seats	<input type="checkbox"/> STEEL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> BUD
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE
MECHANICAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> EXHAUST S/D? S_
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SUSPENSION
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> AIR
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPRING
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PAD
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> WHEEL LIFT
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Batteries replaced 4/26	<input checked="" type="checkbox"/> WINCH

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Rim on one tire is chipped. Unit is in derate/limp mode. Fuel injector line & fuel line leak and need repair/replacing. The exhaust flex pipe is leaking at the flex joint and is bent. The tailpipe is bent and needs replaced. The unit is out of DEF fluid. Active grill shutter is missing, the connector is cut off, and wires are corroded. The upper fan shroud is missing, the upper coolant hose bracket is missing. The AC condenser is missing it's mounting brackets. The left side hold down on the battery is missing which causes the battery to shift and the positive cable to rub against the brake line. The unit will need oil, a fuel filter, engine filter and crankcase filter.

12/4/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.		