

RTR Services Inc. BOX TRUCK CONDITION REPORT				RTR #: 5103333-01			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2023	MILES	93,313	VIN #:	1FDWE3FK6PDD27426		
MAKE:	Ford	GVW:	10,050	BOX HEIGHT	6.5'		
				BOX LENGTH	14'		
MODEL:	E350	WHEELBASE:	138"	COLOR: EXTERIOR:	White		
				INTERIOR:	White		
ENGINE:	7.3 LTR V-8	HP	325	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	6 speed auto	FUEL: ☒ GAS ☐ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO			
DOES MOTOR RUN?		☒ YES ☐ NO		COLLISION DAMAGE? ☐ YES ☒ NO			
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING BRAKES ☐ AIR ☐ HYD ☒ PWR LOCKS ☒ PWR WINDOWS ☐ PWR SEATS ☒ PWR MIRRORS ☒ AIR CONDITIONER ☐ AIR RIDE SEAT D/P _____ ☒ AIR RIDE SUSPENSION ☒ AM FM RADIO ☐ CD / CB? _____ ☐ SLEEPER SIZE? _____ ☐ TRANSLUCENT ROOF ☐ E-TRACK LINING ☒ BOX DOME LIGHT ☒ SIDE DOOR FUEL TANKS ☒ SINGLE GAL _____ ☐ DUAL GAL _____ ☐ MUD FLAPS WHEELS ☐ ALUMINUM ☒ STEEL ☐ BUD ☐ SPOKE ☐ EXHAUST S/D? _____ SUSPENSION ☐ AIR ☐ SPRING ☐ PAD ☐ TANDEM AXLE ☐ ENGINE BRAKE ☐ TOOL BOX _____ ☐ LIFT/TAG AXLE ☐ RAMP ☐ LIFTGATE ☐ CAMERA SYSTEM
	HEADLIGHTS	☐	☒	☐	☐		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☒	☐	☐		
	GRILLE	☐	☒	☐	☐		
	D FRONT FENDER	☐	☒	☐	☐		
	D DOOR	☐	☒	☐	☐		
	D BOX	☐	☒	☐	☐		
	REAR BUMPER	☐	☒	☐	☐		
	TAILLIGHTS	☐	☒	☐	☐		
TIRES	REAR PANEL	☐	☒	☐	☐		
	P FRONT FENDER	☐	☒	☐	☐		
	P FRONT DOOR	☐	☒	☐	☐		
	P BOX	☐	☒	☐	☐		
	TOP	☐	☒	☐	☐		
	D FRONT	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
	D REAR A2 (S/D?)	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
	P FRONT	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
GLASS	P REAR A2 (S/D?)	☐	☒	☐	☐	% 60 SIZE: Lt 225 X 75R X 16	
	SPARE	☐	☐	☐	☒	% SIZE:	
	WINDSHIELD	☐	☒	☐	☐		
	D FRONT DOOR	☐	☒	☐	☐		
	REAR WINDOW	☐	☒	☐	☐		
INTERIOR	P FRONT DOOR	☐	☒	☐	☐		
	MIRRORS	☐	☒	☐	☐		
	DASH	☐	☒	☐	☐		
	DOOR PANELS	☐	☒	☐	☐		
	SEAT(S)	☐	☒	☐	☐		
MECHANICAL	FLOORING	☐	☒	☐	☐		
	HEADLINER	☐	☒	☐	☐		
	SLEEPER	☐	☒	☐	☒		
	BOX	☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
		☐	☒	☐	☐		
	GD	FR	PR	UKN	N/A	COMMENTS:	
ENGINE	☐	☒	☐	☐	☐		
TRANSMISSION	☐	☒	☐	☐	☐		
CLUTCH	☐	☒	☐	☐	☒		
DIFFERENTIALS	☐	☒	☐	☐	☐		
BRAKES	☐	☒	☐	☐	☐		
FRONT END	☐	☒	☐	☐	☐		
REAR END	☐	☒	☐	☐	☐		
BATTERY/ELECTR	☐	☒	☐	☐	☐		
REFRIGERATION	☐	☒	☐	☐	☒		

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified.

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125