

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b> 5103351
YEAR:	2024	
MAKE:	Toro	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO    EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	76614	<input checked="" type="checkbox"/> OPERATIONAL
S/N:	416844221	<input type="checkbox"/> NON-OPERATIONAL
POWER:	23 HP	<input type="checkbox"/> UNTESTABLE
DESCRIPTION:	Used	
SHOT / COUNT / HOUR: 32		
NOTES / COMMENTS: Hours Unverified		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE		

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b>
YEAR:		<b>ACCOUNT</b>
MAKE:		<b>ACCOUNT NAME:</b>
MODEL:		
S/N:		
POWER:		
DESCRIPTION:		
SHOT / COUNT / HOUR:		
NOTES / COMMENTS:		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE		

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b>
YEAR:		<b>ACCOUNT</b>
MAKE:		<b>ACCOUNT NAME:</b>
MODEL:		
S/N:		
POWER:		
DESCRIPTION:		
SHOT / COUNT / HOUR:		
NOTES / COMMENTS:		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE		

1/12/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT) \_\_\_\_\_ DATE \_\_\_\_\_ EMPLOYEE'S SIGNATURE \_\_\_\_\_

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125