

| | | |
|--|---|-----------------------|
| YEAR: 2009 | VIN #: 1FTSE34LX9DA38339 | MILES: 210,107 |
| MAKE: Ford | TYPE: Cargo | |
| MODEL: E350 Econoline | COLOR: EXTERIOR: White | INTERIOR: Gray |
| ENGINE: 5.4 Liter V8 | KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | |
| TRANS: Automatic | FUEL: <input checked="" type="checkbox"/> GAS <input type="checkbox"/> DIESEL <input type="checkbox"/> HYBRID <input type="checkbox"/> ANTIFREEZE TESTED | RATING: |
| DOES MOTOR RUN? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | COLLISION DAMAGE? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | |

PHYSICAL APPEARANCE

| | GD | FR | PR | N/A | COMMENTS | OPTIONS |
|--------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------------------|---|
| BODY | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Damage | <input checked="" type="checkbox"/> PWR STEERING |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> PWR BRAKES |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> PWR LOCKS |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> PWR WINDOWS |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Damaged | <input checked="" type="checkbox"/> PWR MIRRORS |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> CRUISE CONTROL |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> PWR SEATS |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> LEATHER SEATS |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Has paint marks dents | <input type="checkbox"/> 2 ND ROW SEAT |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Worn and has paint on it | <input type="checkbox"/> 3 RD ROW SEAT |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Passenger side tail light is cracked | <input type="checkbox"/> 4 TH ROW SEAT |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> CARGO VAN |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> TILT WHEEL |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input type="checkbox"/> TINTED GLASS |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Collision damage | <input checked="" type="checkbox"/> AIR CONDITIONER |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cargo window is broken on left side | <input type="checkbox"/> REAR AIR | |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> REAR WIPER | |
| TIRES | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input type="checkbox"/> REAR DEFROST |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input type="checkbox"/> SUNROOF |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input checked="" type="checkbox"/> AM FM RADIO |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input type="checkbox"/> CD PLAYER |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input type="checkbox"/> NAVIGATION |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 80 SIZE: 245/75/16 | <input type="checkbox"/> BACKUP CAMERA |
| GLASS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> 4 X 4 |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> TOW PACKAGE |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Missing window | <input type="checkbox"/> EXTENDED LENGTH |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Missing two windows | <input type="checkbox"/> CONVERSION KIT |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> CUSTOM WHEELS |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> SHELVING |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| INTERIOR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Needs deep cleaning | |

| | GD | FR | PR | UKN | N/A | COMMENTS: |
|-------------------|-------------------------------------|--------------------------|--------------------------|-------------------------------------|--------------------------|---|
| MECHANICAL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Unit will crank and has electrical power but will not start |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Batteries replaced 3/26 |

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Both side windows on driver side have no glass. Glass replaced with sheet metal and wood. Unit is believed to need a fuel pump and fuel lines replaced. Does not have fuel pressure.

12/9/25

| | | |
|---|------|----------------------|
| EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE |
| All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above. | | |