

|  |            |   |
|--|------------|---|
| <b>RTR Services Inc.</b><br><b>GENERAL EQUIPMENT</b><br><b>CONDITION REPORT</b>  |            | <b>RTR #:</b> 5121867-01  |
| YEAR:  | 2019       |   |
| MAKE:  | BINGER/ERO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO    EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL:   | VSL07      | <input type="checkbox"/> OPERATIONAL  |
| S/N:   | 910012362  | <input type="checkbox"/> NON-OPERATIONAL  |
| POWER:   | Hyd        | <input checked="" type="checkbox"/> UNTESTABLE  |
| <b>DESCRIPTION:</b> Grape Harvester on a pallet stand with mounting brackets.  |            |   |
| <b>SHOT / COUNT / HOUR:</b>  |            |   |
| <b>NOTES / COMMENTS:</b> Damage noticed on wiring & electrical board.  |            |   |
| <b>THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE</b> |            |   |

|  |            |   |
|--|------------|---|
| <b>RTR Services Inc.</b><br><b>GENERAL EQUIPMENT</b><br><b>CONDITION REPORT</b>  |            | <b>RTR #:</b> 5121867-02  |
| YEAR:  | 2019       |   |
| MAKE:  | BINGER/ERO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO    EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL:   | VSL07      | <input type="checkbox"/> OPERATIONAL  |
| S/N:   | 910012363  | <input type="checkbox"/> NON-OPERATIONAL  |
| POWER:   | Hyd        | <input checked="" type="checkbox"/> UNTESTABLE  |
| <b>DESCRIPTION:</b> Grape Harvester on a pallet stand with mounting brackets. Includes four saw blades.  |            |   |
| <b>SHOT / COUNT / HOUR:</b>  |            |   |
| <b>NOTES / COMMENTS:</b>   |            |   |
| <b>THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE</b> |            |   |

|  |  |                      |
|--|--|----------------------|
| <b>RTR Services Inc.</b><br><b>GENERAL EQUIPMENT</b><br><b>CONDITION REPORT</b>  |  | <b>RTR #:</b>        |
| YEAR:  |  | <b>ACCOUNT</b>       |
| MAKE:  |  | <b>ACCOUNT NAME:</b> |
| MODEL:   |  |                      |
| S/N:   |  |                      |
| POWER:   |  |                      |
| <b>DESCRIPTION:</b>  |  |                      |
| <b>SHOT / COUNT / HOUR:</b>  |  |                      |
| <b>NOTES / COMMENTS:</b>   |  |                      |
| <b>THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE</b> |  |                      |

1/7/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT) \_\_\_\_\_ DATE \_\_\_\_\_ EMPLOYEE'S SIGNATURE \_\_\_\_\_

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125