

YEAR: 2005	VIN #: 1GDM7C1C35F523780	MILES: 119,399
MAKE: GMC	BODY TYPE: Bucket Truck	
MODEL: C7500	GVW: 33,000	COLOR: EXTERIOR: White INTERIOR: Gray
ENGINE: CAT C7 7.2L	KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
TRANS: 6-Speed Manual	FUEL: <input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL <input type="checkbox"/> HYBRID	ANTIFREEZE TESTED: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO RATING
DOES MOTOR RUN? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	COLLISION DAMAGE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	

PHYSICAL APPEARANCE

	GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Slightly Bent	<input checked="" type="checkbox"/> PWR STEERING
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Passenger side is starting to crack	<input checked="" type="checkbox"/> PWR BRAKES
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Handle is broken	<input type="checkbox"/> PWR LOCKS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR WINDOWS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR SEATS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> LEATHER SEATS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Dented and cracked	<input type="checkbox"/> PWR MIRRORS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> CRUISE CONTROL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Metal is chipped and cracked	<input type="checkbox"/> TILT WHEEL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Bent	<input type="checkbox"/> TINTED GLASS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR CONDITIONER
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> CUSTOM WHEELS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AM/FM RADIO
TIRES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14/32 % SIZE: 11R22.5	<input type="checkbox"/> CD PLAYER
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13/32 % SIZE: 11R22.5	<input type="checkbox"/> NAVIGATION
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14/32 % SIZE: 11R22.5	<input type="checkbox"/> BACKUP CAMERA
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13/32 % SIZE: 11R22.5	<input type="checkbox"/> 4 X 4
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> TOW PACKAGE
GLASS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Cracked	<input type="checkbox"/> CUSTOM WHEELS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> UTILITY BODY
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> BUCKET 75'
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> OUTRIGGERS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> TOOL BOX _____
INTERIOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Cracked and missing parts	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Ripped	<input type="checkbox"/>
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Ripped	<input type="checkbox"/>

	GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Batteries replaced 2/26

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Good for -30. Driver side mirror is missing lower portion of glass. Passenger side mirror is disconnected.

1/23/26

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.		