RTR Services Inc. VAN CONDITION REPORT		RTR #:	6013078-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2018	VIN #:	3C6TRVAG0JE103155	MILES:	64,419
MAKE:	Ram	TYPE:	Van		
MODEL:	ProMaster 1500	COLOR: EXTERIOR:	Red	INTERIOR:	Gray / White
ENGINE:	V-6 3.6L	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	Automatic	FUEL: ☒ GAS ☐ DIESEL ☐ HYBRID ☐ ANTIFREEZE TESTED		RATING:	

DOES MOTOR RUN? ☒ YES ☐ NO COLLISION DAMAGE? ☒ YES ☐ NO

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEADLIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	D CARGO DOOR	☐	☐	☐	☒	
	D REAR PANEL	☐	☒	☐	☐	Multiple dents and scratches
	REAR BUMPER	☐	☒	☐	☐	
	TAILLIGHTS	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P CARGO DOOR	☐	☒	☐	☐	
	P REAR PANEL	☐	☒	☐	☐	
	REAR CARGO DR	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	Dents on rear end
TIRES	D FRONT	☐	☐	☒	☐	% 20 SIZE: 255/75R16
	D REAR	☐	☒	☐	☐	% 50 SIZE: 255/75R16
	P FRONT	☐	☐	☒	☐	% 20 SIZE: 255/75R16
	P REAR	☐	☒	☐	☐	% 50 SIZE: 255/75R16
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☐	☒	☐	Rock chips
	D FRONT DOOR	☐	☒	☐	☐	
	D REAR DOOR	☐	☐	☐	☒	
	D REAR PANEL	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	P REAR DOOR	☐	☐	☐	☒	
	P REAR PANEL	☐	☐	☐	☒	
	REAR WINDOW	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	FRONT SEAT(S)	☐	☒	☐	☐	
	REAR SEAT	☐	☐	☐	☒	
	CARPET/FLOORING	☐	☐	☒	☐	Rusted & has holes
	HEADLINER	☐	☒	☐	☐	

OPTIONS	
☒	PWR STEERING
☒	PWR BRAKES
☐	PWR LOCKS
☒	PWR WINDOWS
☐	PWR MIRRORS
☐	CRUISE CONTROL
☐	PWR SEATS
☒	LEATHER SEATS
☐	2ND ROW SEAT
☐	3RD ROW SEAT
☐	4TH ROW SEAT
☒	CARGO VAN
☒	TILT WHEEL
☐	TINTED GLASS
☒	AIR CONDITIONER
☐	REAR AIR
☐	REAR WIPER
☐	REAR DEFROST
☐	SUNROOF
☒	AM FM RADIO
☐	CD PLAYER
☐	NAVIGATION
☒	BACKUP CAMERA
☐	4 X 4
☐	TOW PACKAGE
☐	EXTENDED LENGTH
☐	CONVERSION KIT
☐	CUSTOM WHEELS
☐	SHELVING
☐	
☐	
☐	
☐	
☐	
☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified.

2/10/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125