RTR Services Inc. HEAVY TRUCK CONDITION REPORT		RTR #:	6013322-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2019	MILES	825,992	VIN #:	4V4NC9EH0KN197052						
MAKE:	Volvo	GVW:		LICENSE:		ST:		TAGS:	MONTH		YR:
MODEL:	VNL 760	WHEELBASE:		COLOR: EXTERIOR:	White	INTERIOR:	Gray				
ENGINE:	Volvo D13 12.8L	HP		BODY TYPE:	Sleeper	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:					
DOES MOTOR RUN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO						

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	Passenger side scraped / broken
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D SLEEPER	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	Grating on rear passenger side is bent
	TAILLIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P SLEEPER	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	D REAR A2 (S/D?)	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	P FRONT	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	P REAR A2 (S/D?)	☐	☒	☐	☐	25 % 11R22.5 SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☒ PWR LOCKS
- ☒ PWR WINDOWS
- ☒ PWR SEATS
- ☒ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☒ AIR RIDE SEAT D/P
- ☒ AIR RIDE SUSPENSION
- ☐ CONV. 5TH WHEEL
- ☒ SLIDING 5TH WHEEL
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☒ SLEEPER SIZE? Twin
- ☒ ELECTRICAL PIGTAIL
- ☒ GLAD HANDS
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☒ ALUMINUM
  - ☐ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S
- SUSPENSION
  - ☒ AIR
  - ☐ SPRING
  - ☐ PAD
- ☒ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX
- ☐ LIFT/TAG AXLE
- ☐ WET KIT
- ☐
- ☐
- ☐
- ☐
- ☐

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified.

1-29-26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125