RTR Services Inc. UTILITY TRUCK CONDITION REPORT		RTR #:	6023369-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2003	VIN #:	1M2K189C53M021548			MILES:	42,732
MAKE:	Mack	BODY TYPE:	Concrete Pump				
MODEL:	MR688S	GVW:		COLOR: EXTERIOR:	White	INTERIOR:	Black
ENGINE:	Mack E7 12L	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	10Spd Manual	FUEL: ☐ GAS ☒ DIESEL ☐ HYBRID		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING	
DOES MOTOR RUN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO		

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING
	HEADLIGHTS	☐	☒	☐	☐		☒ PWR BRAKES
	HOOD	☐	☒	☐	☐		☐ PWR LOCKS
	TURN SIGNALS	☐	☒	☐	☐		☐ PWR WINDOWS
	GRILLE	☐	☒	☐	☐		☐ PWR SEATS
	D FRONT FENDER	☐	☒	☐	☐		☐ LEATHER SEATS
	D DOOR	☐	☒	☐	☐		☐ PWR MIRRORS
	D REAR FENDER	☐	☒	☐	☐		☐ CRUISE CONTROL
	CARGO BED	☐	☐	☐	☒		☐ TILT WHEEL
	REAR BUMPER	☐	☐	☐	☒		☐ TINTED GLASS
	TAILLIGHTS	☐	☒	☐	☐		☐ AIR CONDITIONER
	TAILGATE	☐	☐	☐	☒		☐ CUSTOM WHEELS
	P FRONT FENDER	☐	☒	☐	☐		☐ AM/FM RADIO
	P DOOR	☐	☒	☐	☐		☐ CD PLAYER
	P REAR FENDER	☐	☒	☐	☐		☐ NAVIGATION
	TOP	☐	☒	☐	☐		☐ BACKUP CAMERA
TIRES	D FRONT	☐	☒	☐	☐	50 % SIZE: 425/65 R 22.5	☐ 4 X 4
	D REAR	☐	☒	☐	☐	20 % SIZE: 11 R 22.5	☐ TOW PACKAGE
	P FRONT	☐	☒	☐	☐	50 % SIZE: 425/65 R 22.5	☐ CUSTOM WHEELS
	P REAR	☐	☒	☐	☐	20 % SIZE: 11 R 22.5	☐ SUNROOF
	SPARE	☐	☐	☐	☒	% SIZE:	☐ UTILITY BODY
GLASS	WINDSHIELD	☐	☒	☐	☐		☐ BUCKET _____
	D FRONT DOOR	☐	☒	☐	☐		☒ OUTRIGGERS
	D REAR PANEL	☐	☐	☐	☒		☐ TOOL BOX _____
	P FRONT DOOR	☐	☒	☐	☐		☐
	P REAR PANEL	☐	☒	☐	☐		☐
	REAR WINDOW	☐	☐	☐	☒		☐
INTERIOR	DASH	☐	☒	☐	☐		☐
	DOOR PANELS	☐	☒	☐	☐		☐
	SEAT(S)	☐	☒	☐	☐		☐
	CARPET	☐	☒	☐	☐		☐
	HEADLINER	☐	☒	☐	☐		☐

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☐	☒	☐	☐	Battery replaced 05/15, a jump start was still required for each start when testing.

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. The boom is non operational. The control panel has some corrosion and is not properly assembled. The hydraulic fluid is low. The boom may be partially filled with concrete and could need replacing.

2/17/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125