| RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT | | RTR #: | 6023378-01 |
|---|---|---|---|
| | | ACCOUNT | |
| | | ACCOUNT NAME: | |

| YEAR: | 2024 | BODY TYPE: | Equipment Trailer | VIN #: | 1A920026771361195 | | |
|---|---|---|---|---|---|---|---|
| MAKE: | Allen's MFG | CAR CAPACITY | | | | | |
| MODEL: | EQ18TA | COLOR: | EXTERIOR: | Green | | | |
| LENGTH: | 18' | WIDTH: | 102" | HEIGHT: | 3'6" | GVW: | N/A |

HITCH: ☐ GOOSE NECK ☐ PINTLE ☐ 5TH WHEEL PIN ☐ 1 7/8" BALL ☐ 2" BALL ☒ 2 5/16" BALL

| CAN IT BE TOWED? | ☒ YES | ☐ NO | COLLISION DAMAGE? | ☐ YES | ☒ NO | KEYS: | ☐ YES | ☒ NO |
|---|---|---|---|---|---|---|---|---|

## PHYSICAL APPEARANCE

| | | GD | FR | PR | N/A | COMMENTS |
|---|---|---|---|---|---|---|
| BODY | FRONT PANEL | ☐ | ☒ | ☐ | ☐ | |
| | HITCH | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE TIE DOWNS | ☐ | ☐ | ☐ | ☒ | |
| | REAR PANEL | ☐ | ☒ | ☐ | ☐ | |
| | P SIDE TIE DOWNS | ☐ | ☐ | ☐ | ☒ | |
| | P SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | REAR BUMPER | ☐ | ☒ | ☐ | ☐ | |
| | TOP | ☐ | ☒ | ☐ | ☐ | |
| | RAMP(S) | ☐ | ☒ | ☐ | ☐ | |
| | SIDE DOOR | ☐ | ☐ | ☐ | ☒ | |
| | REAR DOOR | ☐ | ☐ | ☐ | ☒ | |
| TIRES | D REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 80 SIZE: 235/85R16 |
| | D REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 80 SIZE: 235/85R16 |
| | D REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | P REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 80 SIZE: 235/85R16 |
| | P REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 80 SIZE: 235/85R16 |
| | P REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | SPARE | ☐ | ☒ | ☐ | ☐ | % 100 SIZE: 235/85R16 |

| | | GD | FR | PR | UKN | N/A | COMMENTS: |
|---|---|---|---|---|---|---|---|
| MECHANICAL | TAILLIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SIGNAL LIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | CLEARANCE LGT | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SLIDER AXLES | ☐ | ☐ | ☐ | ☐ | ☒ | |
| | LANDING GEAR | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | AIR HOSE/GLAD | ☐ | ☐ | ☐ | ☐ | ☒ | |
| | ELECTRIC PIGTAIL | ☐ | ☒ | ☐ | ☐ | ☐ | Battery replaced 2/26 |

### OPTIONS

- ☐ AIR RIDE SUSPENSION
- ☒ SPRING SUSPENSION
- ☐ AIR BRAKES
- ☒ ELECTRICAL BRAKES
- ☐ HYD BRAKES
- ☐ SLIDER AXLE

WHEELS

- ☐ BUD
- ☐ SPOKE
- ☒ STEEL
- ☐ ALUMINUM

- ☒ TOOL BOX _____
- ☐ MUD FLAPS
- ☒ LOADING RAMP
- ☒ BATTERY
- ☐ DOVE TAIL
- ☐ TILT BED
- ☐ WEDGE
- ☐ WINCH
- ☒ SPARE TIRE RACK
- ☐ REAR DOOR
- ☐ TANDEM AXLE
- ☐ SIDE DOOR
- ☐ LIFT/TAG AXLE
- ☐ ENCLOSED

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS:

2/11/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.



The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125