

RTR Services Inc. DUMP TRUCK CONDITION REPORT				RTR #: 6023928-01			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2003	MILES	162864	VIN #:	1HTWYAHT93J074896		
MAKE:	International	GVW:		BED HEIGHT	4'		
MODEL:	7600	WHEELBASE:		BED LENGTH	15'		
ENGINE:	Cummins ISM	HP		COLOR: EXTERIOR:	White		
TRANS:	Manual 8LL	FUEL:	☐ GAS ☒ DIESEL	INTERIOR:	Black/ Gray		
		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:			
DOES MOTOR RUN? ☒ YES ☐ NO		COLLISION DAMAGE? ☐ YES ☒ NO					
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING BRAKES ☒ AIR ☐ HYD ☐ PWR LOCKS ☐ PWR WINDOWS ☐ PWR SEATS ☐ PWR MIRRORS ☒ AIR CONDITIONER ☒ AIR RIDE SEAT D/P _____ ☒ AIR RIDE SUSPENSION ☐ AM FM RADIO ☐ CD / CB? _____ ☐ HITCH TYPE _____ ☒ TARP SYSTEM ☒ TANDEM AXLE ☐ ENGINE BRAKE ☐ TOOL BOX _____ FUEL TANKS ☐ SINGLE GAL _____ ☒ DUAL GAL _____ ☒ MUD FLAPS WHEELS ☐ ALUMINUM ☒ STEEL ☐ BUD ☐ SPOKE ☒ EXHAUST S/D? S_ _____ SUSPENSION ☐ AIR ☒ SPRING ☐ PAD ☐ LIFT/ TAG AXLE ☐ ARTICULATED ☐ BED CAPACITY _____ ☐ WET KIT
	HEADLIGHTS	☐	☒	☐	☐		
	HOOD	☐	☒	☐	☐		
	TURN SIGNALS	☐	☒	☐	☐		
	GRILLE	☐	☒	☐	☐		
	D FRONT FENDER	☐	☒	☐	☐		
	D DOOR	☐	☒	☐	☐	Door is rusty	
	D DUMP BED	☐	☒	☐	☐		
	REAR GATE	☐	☒	☐	☐		
	TAILLIGHTS	☐	☒	☐	☐		
TIRES	REAR PANEL	☐	☒	☐	☐		
	P FRONT FENDER	☐	☒	☐	☐		
	P FRONT DOOR	☐	☒	☐	☐		
	P DUMP BED	☐	☒	☐	☐		
	TOP	☐	☒	☐	☐		
	D FRONT	☐	☒	☐	☐	% 10 SIZE:	
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE:	
GLASS	D REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE:	
	P FRONT	☐	☒	☐	☐	% 10 SIZE:	
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE:	
	P REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE:	
	SPARE	☐	☐	☐	☒	% SIZE:	
	WINDSHIELD	☐	☒	☐	☐		
	D FRONT DOOR	☐	☒	☐	☐		
INTERIOR	REAR WINDOW	☐	☒	☐	☐		
	P FRONT DOOR	☐	☒	☐	☐		
	MIRRORS	☐	☒	☐	☐		
	DASH	☐	☒	☐	☐		
	DOOR PANELS	☐	☒	☐	☐		
	SEAT(S)	☐	☒	☐	☐	Rip in drivers seat	
	FLOORING	☐	☒	☐	☐		
MECHANICAL	HEADLINER	☐	☒	☐	☐		
	DUMP BED	☐	☒	☐	☐	Rust in bed	
		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
FRONT END	☐	☒	☐	☐	☐		
REAR END	☐	☒	☐	☐	☐		
BATTERY/ELECTR	☐	☐	☒	☐	☐	Jump start required. Batteries need replacing.	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE							
COMMENTS: Mileage Unverified. Runs and Drives							

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125