

<b>RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT</b>	 	<b>RTR #:</b> 6033370-03	<b>ACCOUNT</b>
		<b>ACCOUNT NAME:</b>	

<b>YEAR:</b> 2019	<b>BODY TYPE:</b> Flatbed	<b>VIN #:</b> 5Z5BD2225KS000290
<b>MAKE:</b> Appalachian	<b>CAR CAPACITY:</b> 1	
<b>MODEL:</b> CG-FDW	<b>COLOR:</b> EXTERIOR: Black	
<b>LENGTH:</b> 22'	<b>WIDTH:</b> 8'6"	<b>HEIGHT:</b> 88" <b>GVW:</b> 13,000
<b>HITCH:</b> <input type="checkbox"/> GOOSE NECK <input checked="" type="checkbox"/> PINTLE <input type="checkbox"/> 5 <sup>TH</sup> WHEEL PIN <input type="checkbox"/> 1 7/8" BALL <input type="checkbox"/> 2" BALL <input type="checkbox"/> 2 5/16" BALL		
<b>CAN IT BE TOWED?</b> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<b>COLLISION DAMAGE?</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<b>KEYS:</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

**PHYSICAL APPEARANCE**

	GD	FR	PR	N/A	COMMENTS	OPTIONS
<b>BODY</b>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> AIR RIDE SUSPENSION
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPRING SUSPENSION
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> AIR BRAKES
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> ELECTRICAL BRAKES
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> HYD BRAKES
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SLIDER AXLE
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<b>WHEELS</b>
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> BUD
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Passenger side bent forward	<input checked="" type="checkbox"/> STEEL
<b>TIRES</b>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> ALUMINUM
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 235/80R-16	<input checked="" type="checkbox"/> TOOL BOX
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 75 SIZE: 235/80R-16	<input type="checkbox"/> MUD FLAPS
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input checked="" type="checkbox"/> LOADING RAMP
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 235/80R-16	<input type="checkbox"/> BATTERY
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 75 SIZE: 235/80R-16	<input type="checkbox"/> DOVE TAIL
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% 100 SIZE: 235/80R-16; Tire Rim is damaged	<input type="checkbox"/> TILT BED
<b>MECHANICAL</b>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> WEDGE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> WINCH
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPARE TIRE RACK
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> REAR DOOR
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> TANDEM AXLE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SIDE DOOR
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> LIFT/TAG AXLE
						<input type="checkbox"/> ENCLOSED

**THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE**

**COMMENTS:** Brakes need work. Deck height is 28"

_____ EMPLOYEE'S FULL NAME (PLEASE PRINT)	3/24/26 DATE	_____ EMPLOYEE'S SIGNATURE
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.		