RTR Services Inc. VAN CONDITION REPORT		RTR #:	6063410-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2021	VIN #:	1FTBW3X84MKA91711	MILES:	44,976
MAKE:	Ford	TYPE:	Cargo Van		
MODEL:	T-350	COLOR: EXTERIOR:	White	INTERIOR:	Gray
ENGINE:	V6 3.5L	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	Automatic	FUEL: ☒ GAS ☐ DIESEL ☐ HYBRID ☐ ANTIFREEZE TESTED		RATING:	
DOES MOTOR RUN?	☒ YES ☐ NO	COLLISION DAMAGE?	☒ YES ☐ NO		

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING
	HEADLIGHTS	☐	☒	☐	☐		☒ PWR BRAKES
	HOOD	☐	☒	☐	☐		☒ PWR LOCKS
	TURN SIGNALS	☐	☒	☐	☐		☒ PWR WINDOWS
	GRILLE	☐	☒	☐	☐		☒ PWR MIRRORS
	D FRONT FENDER	☐	☒	☐	☐		☐ CRUISE CONTROL
	D FRONT DOOR	☐	☒	☐	☐		☐ PWR SEATS
	D CARGO DOOR	☐	☒	☐	☐		☐ LEATHER SEATS
	D REAR PANEL	☐	☒	☐	☐		☐ 2ND ROW SEAT
	REAR BUMPER	☐	☐	☒	☐	Dented	☐ 3RD ROW SEAT
	TAILLIGHTS	☐	☒	☐	☐		☐ 4TH ROW SEAT
	P FRONT FENDER	☐	☒	☐	☐		☒ CARGO VAN
	P FRONT DOOR	☐	☒	☐	☐		☐ TILT WHEEL
	P CARGO DOOR	☐	☐	☒	☐	Dented; Broken off door handle	☐ TINTED GLASS
	P REAR PANEL	☐	☒	☐	☐		☒ AIR CONDITIONER
	REAR CARGO DR	☐	☒	☐	☐		☐ REAR AIR
	TOP	☐	☒	☐	☐		☐ REAR WIPER
TIRES	D FRONT	☐	☒	☐	☐	% 40 SIZE:	☐ REAR DEFROST
	D REAR	☐	☒	☐	☐	% 40 SIZE:	☐ SUNROOF
	P FRONT	☐	☒	☐	☐	% 40 SIZE:	☒ AM FM RADIO
	P REAR	☐	☒	☐	☐	% 40 SIZE:	☐ CD PLAYER
	SPARE	☐	☐	☐	☒	% SIZE:	☐ NAVIGATION
GLASS	WINDSHIELD	☐	☒	☐	☐		☐ BACKUP CAMERA
	D FRONT DOOR	☐	☒	☐	☐		☐ 4 X 4
	D REAR DOOR	☐	☒	☐	☐	Dent on back right door panel near the tailight	☐ TOW PACKAGE
	D REAR PANEL	☐	☒	☐	☐		☐ EXTENDED LENGTH
	P FRONT DOOR	☐	☒	☐	☐		☐ CONVERSION KIT
	P REAR DOOR	☐	☒	☐	☐	Dent along side	☐ CUSTOM WHEELS
	P REAR PANEL	☐	☒	☐	☐		☒ SHELVING
	REAR WINDOW	☐	☒	☐	☐		☐
INTERIOR	DASH	☐	☒	☐	☐		☐
	DOOR PANELS	☐	☒	☐	☐		☐
	FRONT SEAT(S)	☐	☒	☐	☐		☐
	REAR SEAT	☐	☐	☐	☒		☐
	CARPET/FLOORING	☐	☒	☐	☐		☐
	HEADLINER	☐	☒	☐	☐		☐

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	BRAKES	☐	☒	☐	☐	☐	Pads are worn, needs service
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Low fuel,

7/14/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125