RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	6073246
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2022	VIN/SN:	L23GT0127						
MAKE:	TEUPEN	☐ WHEEL ☒ TRACK ☐ STATIONARY ☐ SKIDMOUNTED							
MODEL:	TC69A	COLOR: EXTERIOR:	Gray	INTERIOR:	N/A				
ENGINE:	Kubota	HP:		KEYS: IGNITION: ☐ YES ☐ NO ☒ N/A • DOOR: ☐ YES ☒ NO ☐ N/A					
TRANS:	Hyd	FUEL: ☒ DIESEL ☐ GAS ☐ PROPANE ☐ CNG ☐ ELECTRIC ☐ HYDRAULIC							
HRS:	616	DOES IT RUN?	☒ YES	☐ NO	☐ UNK				
		LENGTH:		WIDTH:		HEIGHT:		WEIGHT:	

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT	☐	☒	☐	☐		☐ PWR STEERING
	HEAD LIGHTS	☐	☐	☐	☒		☐ PWR BRAKES
	HOOD	☐	☐	☐	☒		☐ ENCLOSED CAB
	TURN SIGNALS	☐	☐	☐	☒		☐ TINTED GLASS
	GRILLE	☐	☐	☐	☒		☐ AIR CONDITIONER
	L FRONT FENDER	☐	☐	☐	☒		☐ HEATER
	L DOOR	☐	☐	☐	☒		☐ AIR RIDE SEAT
	L REAR PANEL	☐	☐	☐	☒		☐ AIR RIDE SUSPENSION
	SAFETY LIGHTS	☐	☐	☐	☒		☐ AM FM RADIO
	REAR	☐	☒	☐	☐		☐ TAPE DECK
	TAIL LIGHTS	☐	☐	☐	☒		☐ CD PLAYER
	FRAME	☐	☒	☐	☐		☐ MUD FLAPS
	TURN SIGNALS	☐	☐	☐	☒		☐ 2WD
	R FRONT FENDER	☐	☐	☐	☒		☐ 4WD
	R FRONT DOOR	☐	☐	☐	☒		☐ PTO
	R REAR PANEL	☐	☒	☐	☐		☐ BLADE
	WORK LIGHTS	☐	☐	☐	☒		☐ BUCKET SIZE _____
	TOP	☐	☒	☐	☐		☐ RIPPER _____
TIRES	L FRONT	☐	☒	☐	☐	Tracks % SIZE:	☐ ROLLER _____
	L REAR	☐	☐	☐	☒	% SIZE:	☐ COMPACTOR _____
	R FRONT	☐	☒	☐	☐	Tracks % SIZE:	☐ BOOM _____
	R REAR	☐	☐	☐	☒	% SIZE:	☐ TRENCHER _____
GLASS	WINDSHIELD	☐	☐	☐	☒		☐ SCRAPER _____
	L DOOR	☐	☐	☐	☒		☐ TRACK WIDTH _____
	REAR WINDOW	☐	☐	☐	☒		☐ GENERATOR
	R DOOR	☐	☐	☐	☒		VOLTS _____
	MIRRORS	☐	☐	☐	☒		WATTS _____
INTERIOR	DASH/GAUGES	☐	☒	☐	☐		☐ COMPRSR CFM _____
	DOOR PANELS	☐	☒	☐	☐		☐ TANK SIZE GAL _____
	SEAT	☐	☐	☐	☒		☐ HITCH _____
	CARPET/MAT	☐	☐	☐	☒		☐ ROP
	CONTROLS	☐	☒	☐	☐		☐ FUEL TANKS _____

		GD	FR	PR	UKN	N/A	COMMENTS:	
MECHANICAL	ENGINE	☐	☒	☐	☐	☐		☐ AUXILIARY HYDS
	TRANSMISSION	☐	☒	☐	☐	☐		☐
	CLUTCH	☐	☒	☐	☐	☐		☐
	DIFFERENTIAL	☐	☒	☐	☐	☐		☐
	2ND DIFFERENTIAL	☐	☒	☐	☐	☐		☐
	UNDERCARRIAGE	☐	☒	☐	☐	☐		☐
	BRAKES	☐	☒	☐	☐	☐		☐
	FRONT END	☐	☒	☐	☐	☐		☐
	REAR END	☐	☒	☐	☐	☐		☐
	BATTERY/ELECTR	☒	☐	☐	☐	☐	Battery kill switch and battery replaced 11/2026	☐

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Hours unverfied. Unit comes with remote to operate.

10/1/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107