
RTR Services Inc.
BOX TRUCK
CONDITION REPORT



RTR #: 6073352
ACCOUNT NUMBER:
ACCOUNT NAME:

YEAR:	2022	**MILES**	179,732	**VIN #:**	1F64F5KN3N0A02955				
MAKE:	Ford	**GVW:**	**16,000**	**BOX HEIGHT**	10 ft	**BOX LENGTH**	14 ft	**BOX WIDTH**	95 in
MODEL:	F-59 P700	**WHEELBASE:**	158 in	**COLOR: EXTERIOR:**	White			**INTERIOR:**	Gray
ENGINE:	Ford 7.3L V8	**HP**		**KEYS: IGNITION:** ☒ YES ☐ NO • **DOOR:** ☐ YES ☒ NO					
TRANS:	Automatic	**FUEL:** ☒ GAS ☐ DIESEL		**ANTIFREEZE TESTED:** ☐ YES ☒ NO				**RATING:**	
DOES MOTOR RUN?	☒ YES	☐ NO	**COLLISION DAMAGE?**	☐ YES	☒ NO				

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☐	☒	☐	Bumper is missing on driver side
	HEADLIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	Dented
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAILLIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	% 50 **SIZE:** 225/70R19.5
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 75 **SIZE:** 225/70R19.5
	D REAR A2 (S/D?)	☐	☐	☐	☒	% **SIZE:**
	P FRONT	☐	☒	☐	☐	% 50 **SIZE:** 225/70R19.5
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 75 **SIZE:** 225/70R19.5
	P REAR A2 (S/D?)	☐	☐	☐	☒	% **SIZE:**
	SPARE	☐	☐	☐	☒	% **SIZE:**
GLASS	WINDSHIELD	☐	☐	☒	☐	Cracked
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	Loose, Dented
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☐	☐	☒	
	SLEEPER	☐	☐	☐	☒	
	BOX	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☒	☐	☐	Runs rough and stalls, oil change light on.
	TRANSMISSION	☐	☐	☒	☐	☐	Transmission will need to be replaceded.
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☐	☐	☒	☐	
	REAR END	☐	☐	☐	☒	☐	
	BATTERY/ELECTR	☒	☐	☐	☐	☐	New Battery 9/2026
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☐ AIR
  - ☒ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☐ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P _____
- ☐ AIR RIDE SUSPENSION
- ☒ AM FM RADIO
- ☐ CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☒ TRANSLUCENT ROOF
- ☐ E-TRACK LINING
- ☐ BOX DOME LIGHT
- ☐ SIDE DOOR
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☐ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☒ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S_
- SUSPENSION
  - ☐ AIR
  - ☒ SPRING
  - ☐ PAD
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX _____
- ☐ LIFT/TAG AXLE
- ☐ RAMP
- ☐ LIFTGATE
- ☒ CAMERA SYSTEM

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Unit starts but will only run for a short time and shuts down. Gas cap is missing and due to exposure, the fuel tank and line will need to be drained and flushed.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125