

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 6073748 ACCOUNT NUMBER: ACCOUNT NAME:					
YEAR:	1994	VIN/SN:	57B0394516				
MAKE:	Power Curbers	☐ WHEEL ☒ TRACK ☐ STATIONARY ☐ SKIDMOUNTED					
MODEL:	5700B	COLOR:	EXTERIOR: Grey INTERIOR: N/A				
ENGINE:	4-Cyl	HP:	87 KEYS: IGNITION: ☒ YES ☐ NO ☐ N/A • DOOR: ☐ YES ☐ NO ☒ N/A				
TRANS:	Hyd	FUEL: ☒ DIESEL ☐ GAS ☐ PROPANE ☐ CNG ☐ ELECTRIC ☐ HYDRAULIC					
HRS:	3,367	DOES IT RUN? ☒ YES ☐ NO ☐ UNK					
		LENGTH:	20 ft WIDTH: 8 ft 6in HEIGHT: 8ft 1 in WEIGHT: 24,000LB				
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT	☐	☐	☒	☐		☒ PWR STEERING
	HEAD LIGHTS	☐	☐	☐	☒		☒ PWR BRAKES
	HOOD	☐	☐	☐	☒		☐ ENCLOSED CAB
	TURN SIGNALS	☐	☐	☐	☒		☐ TINTED GLASS
	GRILLE	☐	☐	☐	☒		☐ AIR CONDITIONER
	L FRONT FENDER	☐	☐	☐	☒		☐ HEATER
	L DOOR	☐	☐	☐	☒		☐ AIR RIDE SEAT
	L REAR PANEL	☐	☐	☐	☒		☐ AIR RIDE SUSPENSION
	SAFETY LIGHTS	☐	☐	☐	☒		☐ AM FM RADIO
	REAR	☐	☐	☒	☐		☐ TAPE DECK
	TAIL LIGHTS	☐	☐	☐	☒		☐ CD PLAYER
	FRAME	☐	☐	☒	☐	Scratches, Rusting, Concrete buildup throughout body	☐ MUD FLAPS
	TURN SIGNALS	☐	☐	☐	☒		☐ 2WD
	R FRONT FENDER	☐	☐	☒	☐		☐ 4WD
	R FRONT DOOR	☐	☐	☒	☐		☐ PTO
R REAR PANEL	☐	☐	☒	☐		☐ BLADE	
WORK LIGHTS	☐	☐	☒	☐		☐ BUCKET SIZE _____	
TOP	☐	☐	☒	☐		☐ RIPPER _____	
TIRES	L FRONT	☐	☐	☐	☒	% SIZE: _____	☐ ROLLER _____
	L REAR	☐	☐	☐	☒	% SIZE: _____	☐ COMPACTOR _____
	R FRONT	☐	☐	☐	☒	% SIZE: _____	☐ BOOM _____
	R REAR	☐	☐	☐	☒	% SIZE: _____	☐ TRENCHER _____
GLASS	WINDSHIELD	☐	☐	☐	☒		☐ SCRAPER _____
	L DOOR	☐	☐	☐	☒		☒ TRACK WIDTH <u>12in</u>
	REAR WINDOW	☐	☐	☐	☒		☐ GENERATOR
	R DOOR	☐	☐	☐	☒		VOLTS _____
	MIRRORS	☐	☐	☐	☒		WATTS _____
INTERIOR	DASH/GAUGES	☐	☐	☒	☐		☐ COMPRSR CFM _____
	DOOR PANELS	☐	☐	☐	☒		☒ TANK SIZE GAL <u>75</u>
	SEAT	☐	☐	☐	☒		☐ HITCH _____
	CARPET/MAT	☐	☐	☐	☒		☐ ROP
	CONTROLS	☐	☐	☒	☐		☒ FUEL TANKS <u>30</u>
		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	DIFFERENTIAL	☐	☐	☐	☒	☐	
	2 ND DIFFERENTIAL	☐	☐	☐	☒	☐	
	UNDERCARRIAGE	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☐	☒	
REAR END	☐	☐	☐	☐	☒		
BATTERY/ELECTR	☒	☐	☐	☐	☐	Battery Replaced 08/26 / Corrosion on wiring	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE COMMENTS: Hours Unverified.							

9/2/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107