RTR Services Inc. DUMP TRUCK CONDITION REPORT			RTR #:	6083495
			ACCOUNT NUMBER:	
			ACCOUNT NAME:	

YEAR:	2009	MILES	Unknown	VIN #:	2FZHCHBS89AAF8352				
MAKE:	Sterling	GVW:	33,000	BED HEIGHT	4'	BED LENGTH	16'	BED WIDTH	8'
MODEL:	Acterra	WHEELBASE:	212	COLOR: EXTERIOR:	White	INTERIOR:	Grey		
ENGINE:	Cummins 8.3L	HP	215	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Auto	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:			

DOES MOTOR RUN? ☐ YES ☒ NO COLLISION DAMAGE? ☐ YES ☒ NO

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEADLIGHTS	☐	☒	☐	☐	
	HOOD	☐	☐	☒	☐	Crack on Hood
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D DUMP BED	☐	☒	☐	☐	Ripped Tarp
	REAR GATE	☐	☒	☐	☐	
	TAILLIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P DUMP BED	☐	☐	☒	☐	Rust/Holes
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 11R22.5
	D REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 11R22.5
	P FRONT	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 11R22.5
	P REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 11R22.5
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☐	☒	☐	Underneath wires hanging. Cover Missing
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	FLOORING	☐	☐	☒	☐	
	HEADLINER	☐	☒	☐	☐	
	DUMP BED	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	Vehicle non-operational
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	DIFFERENTIALS	☐	☐	☐	☒	☐	Driveline in cab
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☒	☐	
	REAR END	☐	☐	☐	☒	☐	
	BATTERY/ELECTR	☐	☐	☐	☒	☐	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☐ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P _____
- ☐ AIR RIDE SUSPENSION
- ☐ AM FM RADIO
- ☐ CD / CB? _____
- ☐ HITCH TYPE _____
- ☐ TARP SYSTEM
- ☒ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX _____
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☒ ALUMINUM
  - ☐ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S_
- SUSPENSION
  - ☐ AIR
  - ☒ SPRING
  - ☐ PAD
- ☐ LIFT/ TAG AXLE
- ☐ ARTICULATED
- ☐ BED CAPACITY _____
- ☐ WET KIT
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. The batteries need replaced, the timing cover seal and front structure seal both need replaced and are leaking oil.

10/28/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125