
RTR Services Inc. BOX TRUCK CONDITION REPORT		RTR #:	6083714
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2015	MILES	244,597	VIN#:	3ALACWDT1FDGF5192				
MAKE:	Freightliner	GVW:	26,000	BOX HEIGHT	9'	BOX LENGTH	26'	BOX WIDTH	8'
MODEL:	M2	WHEELBASE:	270"	COLOR: EXTERIOR:	White	INTERIOR:	Black		
ENGINE:	Cummins ISB 6.7L	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Allison Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:			
DOES MOTOR RUN?	☐ YES	☒ NO	CAN IT BE DRIVEN?	☐ YES	☒ NO	COLLISION DAMAGE?	☐ YES	☒ NO	

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☒	☐	☐	Rear door can only open partially
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☐	☒	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☐	☒	☐	Box is damaged at top
	TOP	☐	☐	☒	☐	
TIRES	D FRONT	☐	☒	☐	☐	17/32 % 295/75/R22.5 SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	20/32 % 295/75/R22.5 SIZE:
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☒	☐	☐	19/32 % 295/75/R22.5 SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	20/32 % 295/75/R22.5 SIZE:
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☐	☐	☒	
	BOX	☐	☐	☒	☐	Damage to side panel, wood has water damage.

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☒	☐	☐	Serpentine belt off
	TRANSMISSION	☐	☐	☐	☒	☐	Alternator disconnected
	CLUTCH	☐	☐	☐	☒	☐	Turbocharger missing
	DIFFERENTIALS	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☒	☐	
	REAR END	☐	☐	☐	☒	☐	
	BATTERY/ELECTR	☒	☐	☐	☐	☐	Batteries replaced 8/2026
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS	
☒	PWR STEERING
BRAKES	
☒	AIR
☐	HYD
☐	PWR LOCKS
☐	PWR WINDOWS
☐	PWR SEATS
☐	PWR MIRRORS
☐	AIR CONDITIONER
☒	AIR RIDE SEAT D/P D
☒	AIR RIDE SUSPENSION
☐	AM FM RADIO
☒	TAPE / CD / CB? CD
☐	SLEEPER SIZE? _____
☐	TRANSLUCENT ROOF
☐	E-TRACK LINING
☐	BOX DOME LIGHT
☒	SIDE DOOR
FUEL TANKS	
☐	SINGLE GAL _____
☒	DUAL GAL 50 gal
☐	MUD FLAPS
WHEELS	
☐	ALUMINUM
☒	STEEL
☒	BUD
☐	SPOKE
☒	EXHAUST S/D? Single
SUSPENSION	
☒	AIR
☐	SPRING
☐	PAD
☐	TANDEM AXLE
☒	ENGINE BRAKE
☐	TOOL BOX _____
☐	LIFT/TAG AXLE
☐	RAMP
☒	LIFT GATE
☐	
☐	
☐	
☐	
☐	

COMMENTS: The serpentine belt and alternator are both disconnected and the unit needs oil & anti-freeze. The engine coolant reservoir, engine air cleaner assembly (air filter housing), air filter, and exhaust manifold are uninstalled and in the back of the truck. The unit has damage to the side panel and top of the box, which has left it open to the elements and has caused rainwater to soak the wood in the interior of the box.

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107