


RTR Services Inc. VAN CONDITION REPORT				RTR #: 6083817-05			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2023	VIN #:	VIN: 3C6MRVJG5PE514371		MILES: 72,326		
MAKE:	RAM	TYPE:	Cargo Van				
MODEL:	ProMaster 3500	COLOR:	EXTERIOR: White	INTERIOR:	Black		
ENGINE:	3.6L V6 Gas	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL:	☒ GAS ☐ DIESEL ☐ HYBRID ☐ ANTIFREEZE TESTED	RATING:			
DOES MOTOR RUN?		☒ YES ☐ NO	COLLISION DAMAGE?		☐ YES ☒ NO		
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING
	HEADLIGHTS	☐	☒	☐	☐		☒ PWR BRAKES
	HOOD	☐	☒	☐	☐		☒ PWR LOCKS
	TURN SIGNALS	☐	☒	☐	☐		☒ PWR WINDOWS
	GRILLE	☐	☒	☐	☐		☒ PWR MIRRORS
	D FRONT FENDER	☐	☒	☐	☐		☒ CRUISE CONTROL
	D FRONT DOOR	☐	☒	☐	☐		☐ PWR SEATS
	D CARGO DOOR	☐	☒	☐	☐		☒ LEATHER SEATS
	D REAR PANEL	☐	☒	☐	☐		☐ 2 ND ROW SEAT
	REAR BUMPER	☐	☒	☐	☐		☐ 3 RD ROW SEAT
	TAILLIGHTS	☐	☒	☐	☐		☐ 4 TH ROW SEAT
	P FRONT FENDER	☐	☒	☐	☐		☒ CARGO VAN
	P FRONT DOOR	☐	☒	☐	☐		☐ TILT WHEEL
	P CARGO DOOR	☐	☒	☐	☐		☐ TINTED GLASS
	P REAR PANEL	☐	☒	☐	☐		☒ AIR CONDITIONER
	REAR CARGO DR TOP	☐	☒	☐	☐		☐ REAR AIR
TIRES	D FRONT	☐	☒	☐	☐	% 25 SIZE: 225/75R16C	☐ REAR WIPER
	D REAR	☐	☒	☐	☐	% 25 SIZE: 225/75R16C	☐ REAR DEFROST
	P FRONT	☐	☒	☐	☐	% 25 SIZE: 225/75R16C	☐ SUNROOF
	P REAR	☐	☒	☐	☐	% 25 SIZE: 225/75R16C	☒ AM FM RADIO
	SPARE	☐	☐	☐	☒	% SIZE:	☐ CD PLAYER
							☐ NAVIGATION
GLASS	WINDSHIELD	☐	☒	☐	☐	Cracked	☒ BACKUP CAMERA
	D FRONT DOOR	☐	☒	☐	☐		☐ 4 X 4
	D REAR DOOR	☐	☐	☐	☒		☐ TOW PACKAGE
	D REAR PANEL	☐	☐	☐	☒		☐ EXTENDED LENGTH
	P FRONT DOOR	☐	☐	☐	☒		☐ CONVERSION KIT
	P REAR DOOR	☐	☐	☐	☒		☐ CUSTOM WHEELS
	P REAR PANEL	☐	☐	☐	☒		☐ SHELVING
	REAR WINDOW	☐	☐	☐	☒		☒ Heater
INTERIOR	DASH	☐	☒	☐	☐		☐
	DOOR PANELS	☐	☒	☐	☐		☐
	FRONT SEAT(S)	☐	☒	☐	☐		☐
	REAR SEAT	☐	☒	☐	☐		☐
	CARPET/FLOORING	☐	☒	☐	☐		☐
	HEADLINER	☐	☒	☐	☐		☐
		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE							
COMMENTS: Mileage Unverified. Unit is missing key.							

9/8/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.		

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125