


RTR Services Inc. VAN CONDITION REPORT				RTR #: 6083817-06			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2023	VIN #:	3C6LRVVG9PE590438		MILES: 59,832		
MAKE:	RAM	TYPE:	Cargo Van				
MODEL:	ProMaster 2500	COLOR:	EXTERIOR: White	INTERIOR:	Black		
ENGINE:	V6 3.6L Flex	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL:	☒ GAS ☐ DIESEL ☐ HYBRID ☐ ANTIFREEZE TESTED		RATING:		
DOES MOTOR RUN?		☒ YES ☐ NO	COLLISION DAMAGE?		☐ YES ☒ NO		
PHYSICAL APPEARANCE							
		GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	FRONT BUMPER	☐	☒	☐	☐		☒ PWR STEERING
	HEADLIGHTS	☐	☒	☐	☐		☒ PWR BRAKES
	HOOD	☐	☒	☐	☐		☒ PWR LOCKS
	TURN SIGNALS	☐	☒	☐	☐		☒ PWR WINDOWS
	GRILLE	☐	☒	☐	☐		☒ PWR MIRRORS
	D FRONT FENDER	☐	☒	☐	☐		☐ CRUISE CONTROL
	D FRONT DOOR	☐	☒	☐	☐		☐ PWR SEATS
	D CARGO DOOR	☐	☒	☐	☐		☐ LEATHER SEATS
	D REAR PANEL	☐	☒	☐	☐		☐ 2 ND ROW SEAT
	REAR BUMPER	☐	☒	☐	☐		☐ 3 RD ROW SEAT
	TAILLIGHTS	☐	☒	☐	☐		☐ 4 TH ROW SEAT
	P FRONT FENDER	☐	☒	☐	☐		☒ CARGO VAN
	P FRONT DOOR	☐	☒	☐	☐		☐ TILT WHEEL
	P CARGO DOOR	☐	☒	☐	☐		☐ TINTED GLASS
	P REAR PANEL	☐	☒	☐	☐		☒ AIR CONDITIONER
REAR CARGO DR TOP	☐	☒	☐	☐		☐ REAR AIR	
TIRES	D FRONT	☐	☒	☐	☐	% 50 SIZE: 225/75R16	☐ REAR WIPER
	D REAR	☐	☒	☐	☐	% 50 SIZE: 225/75R16	☐ REAR DEFROST
	P FRONT	☐	☒	☐	☐	% 50 SIZE: 225/75R16	☐ SUNROOF
	P REAR	☐	☒	☐	☐	% 50 SIZE: 225/75R16	☒ AM FM RADIO
	SPARE	☐	☒	☐	☐	% 100 SIZE: 225/75R16	☐ CD PLAYER
GLASS	WINDSHIELD	☐	☒	☐	☐	Cracked	☒ NAVIGATION
	D FRONT DOOR	☐	☒	☐	☐		☐ BACKUP CAMERA
	D REAR DOOR	☐	☒	☐	☐		☐ 4 X 4
	D REAR PANEL	☐	☒	☐	☐		☐ TOW PACKAGE
	P FRONT DOOR	☐	☒	☐	☐		☐ EXTENDED LENGTH
	P REAR DOOR	☐	☒	☐	☐		☐ CONVERSION KIT
	P REAR PANEL	☐	☒	☐	☐		☐ CUSTOM WHEELS
REAR WINDOW	☐	☒	☐	☐		☐ SHELVING	
INTERIOR	DASH	☐	☒	☐	☐		☐
	DOOR PANELS	☐	☒	☐	☐		☐
	FRONT SEAT(S)	☐	☒	☐	☐		☐
	REAR SEAT	☐	☒	☐	☐		☐
	CARPET/FLOORING	☐	☒	☐	☐		☐
		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☒	☐	☐	Runs rough, has a knock
	TRANSMISSION	☐	☐	☒	☐	☐	
	CLUTCH	☐	☐	☒	☐	☐	
	BRAKES	☐	☐	☒	☐	☐	
	FRONT END	☐	☐	☒	☐	☐	
	REAR END	☐	☐	☒	☐	☐	
	BATTERY/ELECTR	☒	☐	☐	☐	☐	Replaced 9/2026
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE							
COMMENTS: Mileage Unverified.							

9/4/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.		

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125