
RTR Services Inc. UTILITY TRUCK CONDITION REPORT		RTR #:	6083984
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2007	VIN #:	1GDE5C1297F414230	MILES:	232,396
MAKE:	GMC	BODY TYPE:	Bucket		
MODEL:	C5500	GVW:	19,500	COLOR: EXTERIOR:	White
ENGINE:	6.6L V8	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO			
TRANS:	Auto	FUEL: ☐ GAS ☒ DIESEL ☐ HYBRID	ANTIFREEZE TESTED: ☒ YES ☐ NO	RATING	

DOES MOTOR RUN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEADLIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D REAR FENDER	☐	☒	☐	☐	
	CARGO BED	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAILLIGHTS	☐	☒	☐	☐	
	TAILGATE	☐	☐	☐	☒	
	P FRONT FENDER	☐	☒	☐	☐	
	P DOOR	☐	☒	☐	☐	
	P REAR FENDER	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	50 % SIZE: 265/70R/9.5
	D REAR	☐	☒	☐	☐	50 % SIZE: 265/70R/9.5
	P FRONT	☐	☒	☐	☐	50 % SIZE: 265/70R/9.5
	P REAR	☐	☒	☐	☐	50 % SIZE: 265/70R/9.5
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	D REAR PANEL	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	P REAR PANEL	☐	☐	☐	☒	
	REAR WINDOW	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☐	☐	☒	
	HEADLINER	☐	☒	☐	☐	

OPTIONS	
☒	PWR STEERING
☒	PWR BRAKES
☒	PWR LOCKS
☐	PWR WINDOWS
☐	PWR SEATS
☒	LEATHER SEATS
☐	PWR MIRRORS
☐	CRUISE CONTROL
☐	TILT WHEEL
☐	TINTED GLASS
☐	AIR CONDITIONER
☐	CUSTOM WHEELS
☒	AM/FM RADIO
☐	CD PLAYER
☐	NAVIGATION
☐	BACKUP CAMERA
☐	4 X 4
☐	TOW PACKAGE
☐	CUSTOM WHEELS
☐	SUNROOF
☐	UTILITY BODY
☒	BUCKET AT37-G
☐	OUTRIGGERS
☒	TOOL BOX _____
☐	
☐	
☐	
☐	
☐	
☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	Runs and drivers but has a lot of noise.
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. The hydraulics work but there is a major oil leak when operating the bucket. Rust on the body, roof, both bumpers, under the doors and inside all the tool boxes. The A/C is non operational.

9/30/26

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125