RTR Services Inc. HEAVY TRUCK CONDITION REPORT		RTR #:	6083994
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2023	MILES	107,102			VIN #:	1XKZDP0X4PJ254515						
MAKE:	Kenworth	GVW:		LICENSE:		ST:		TAGS:		MONTH		YR:	
MODEL:	T880	WHEELBASE:				COLOR: EXTERIOR:	White			INTERIOR:		Gray	
ENGINE:	Paccar MX-13	HP	405	BODY TYPE:	Day Cab	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☐ YES ☐ NO							
TRANS:	Paccar TX-12	FUEL: ☐ GAS ☒ DIESEL				ANTIFREEZE TESTED: ☐ YES ☒ NO				RATING:			
DOES MOTOR RUN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO								

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☐	☒	☐	Missing fender light on passenger side.
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILLE	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D SLEEPER	☐	☐	☐	☒	
	REAR BUMPER	☐	☐	☐	☒	
	TAILLIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☐	☒	☐	Cracks under the headlight
	P FRONT DOOR	☐	☒	☐	☐	
	P SLEEPER	☐	☐	☐	☒	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	30 % SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	30 % SIZE:
	D REAR A2 (S/D?)	☐	☒	☐	☐	30 % SIZE:
	P FRONT	☐	☒	☐	☐	30 % SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	30 % SIZE:
	P REAR A2 (S/D?)	☐	☒	☐	☐	30 % SIZE:
	SPARE	☐	☒	☐	☐	30 % SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☐	☐	☒	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	Check Engine Light On
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☒	☐	☐	☐	☐	New batteries 9/23/2026

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☒ PWR LOCKS
- ☒ PWR WINDOWS
- ☒ PWR SEATS
- ☒ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P
- ☐ AIR RIDE SUSPENSION
- ☐ CONV. 5TH WHEEL
- ☐ SLIDING 5TH WHEEL
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☐ ELECTRICAL PIGTAIL
- ☐ GLAD HANDS
- FUEL TANKS
  - ☐ SINGLE GAL _____
  - ☒ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☒ ALUMINUM
  - ☐ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☐ EXHAUST S/D? _____
- SUSPENSION
  - ☒ AIR
  - ☐ SPRING
  - ☐ PAD
- ☒ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX
- ☐ LIFT/TAG AXLE
- ☐ WET KIT
- ☒ WINCH
- ☐
- ☐
- ☐
- ☐

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS: Mileage Unverified. Fuel/ Air Perssure low.

9/14/2026

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125