| RTR Services Inc. HEAVY TRUCK CONDITION REPORT |  | RTR #: | 6103035 |
|---|---|---|---|
| | | ACCOUNT NUMBER: | |
| | | ACCOUNT NAME: | |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| YEAR: | 2016 | MILES | 188,199 | | | VIN #: | 4V5KC9DF6GN934485 | | | | | | |
| MAKE: | Volvo | GVW: | 28,500 | LICENSE: | WXL7806 | ST: | TX | TAGS: | MONTH | | YR: | | |
| MODEL: | VHD | WHEELBASE: | | | | COLOR: EXTERIOR: | Black/Yellow | | INTERIOR: | | Gray | | |
| ENGINE: | Volvo D11 10.8L | HP | | BODY TYPE: | Cement Mixer | KEYS: IGNITION: ☐ YES ☐ NO • DOOR: ☐ YES ☐ NO | | | | | | | |
| TRANS: | Automatic | FUEL: ☐ GAS ☒ DIESEL | | | | ANTIFREEZE TESTED: ☐ YES ☒ NO | | | RATING: | | | | |
| DOES MOTOR RUN? | ☒ YES | ☐ NO | COLLISION DAMAGE? | ☐ YES | ☒ NO | | | | | | | | |

## PHYSICAL APPEARANCE

| | | GD | FR | PR | N/A | COMMENTS |
|---|---|---|---|---|---|---|
| BODY | FRONT BUMPER | ☐ | ☒ | ☐ | ☐ | |
| | HEAD LIGHTS | ☐ | ☒ | ☐ | ☐ | |
| | HOOD | ☐ | ☐ | ☒ | ☐ | Shows signs of wear |
| | TURN SIGNALS | ☐ | ☒ | ☐ | ☐ | |
| | GRILLE | ☐ | ☒ | ☐ | ☐ | |
| | D FRONT FENDER | ☐ | ☒ | ☐ | ☐ | |
| | D DOOR | ☐ | ☒ | ☐ | ☐ | |
| | D SLEEPER | ☐ | ☐ | ☐ | ☒ | |
| | REAR BUMPER | ☐ | ☒ | ☐ | ☐ | Driver's side is s pushed in a little. |
| | TAILLIGHTS | ☐ | ☒ | ☐ | ☐ | |
| | REAR PANEL | ☐ | ☒ | ☐ | ☐ | |
| | P FRONT FENDER | ☐ | ☒ | ☐ | ☐ | |
| | P FRONT DOOR | ☐ | ☒ | ☐ | ☐ | |
| | P SLEEPER | ☐ | ☐ | ☐ | ☒ | |
| | TOP | ☐ | ☒ | ☐ | ☐ | |
| TIRES | D FRONT | ☐ | ☒ | ☐ | ☐ | 80 % 425/65 R 22.5 SIZE: |
| | D REAR A1 (S/D?) | ☐ | ☐ | ☒ | ☐ | 10 % 11 R 22.5 SIZE: |
| | D REAR A2 (S/D?) | ☐ | ☐ | ☒ | ☐ | 10 % 11 R 22.5 SIZE: |
| | P FRONT | ☐ | ☒ | ☐ | ☐ | 80 % 425/65 R 22.5 SIZE: |
| | P REAR A1 (S/D?) | ☐ | ☐ | ☒ | ☐ | 10 % 11 R 22.5 SIZE: |
| | P REAR A2 (S/D?) | ☐ | ☐ | ☒ | ☐ | 10 % 11 R 22.5 SIZE: |
| | SPARE | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| GLASS | WINDSHIELD | ☐ | ☒ | ☐ | ☐ | |
| | D FRONT DOOR | ☐ | ☒ | ☐ | ☐ | |
| | REAR WINDOW | ☐ | ☒ | ☐ | ☐ | |
| | P FRONT DOOR | ☐ | ☒ | ☐ | ☐ | |
| | MIRRORS | ☐ | ☒ | ☐ | ☐ | |
| INTERIOR | DASH | ☐ | ☒ | ☐ | ☐ | |
| | DOOR PANELS | ☐ | ☒ | ☐ | ☐ | |
| | SEAT(S) | ☐ | ☐ | ☒ | ☐ | Missing passenger seat, driver's seat has duct tape on it |
| | CARPET | ☐ | ☐ | ☐ | ☒ | |
| | HEADLINER | ☐ | ☐ | ☒ | ☐ | Sagging in places |
| | SLEEPER | ☐ | ☐ | ☐ | ☒ | |

| | | GD | FR | PR | UKN | N/A | COMMENTS: |
|---|---|---|---|---|---|---|---|
| MECHANICAL | ENGINE | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | TRANSMISSION | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | CLUTCH | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | DIFFERENTIALS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | BRAKES | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | FRONT END | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | REAR END | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | BATTERY/ELECTR | ☐ | ☒ | ☐ | ☐ | ☐ | |

**OPTIONS**

- ☒ PWR STEERING
- BRAKES
  - ☐ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P
- ☐ AIR RIDE SUSPENSION
- ☐ CONV. 5TH WHEEL
- ☐ SLIDING 5TH WHEEL
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☐ ELECTRICAL PIGTAIL
- ☐ GLAD HANDS
- FUEL TANKS
  - ☐ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☐ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☐ EXHAUST S/D? _____
- SUSPENSION
  - ☐ AIR
  - ☐ SPRING
  - ☐ PAD
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX
- ☐ LIFT/TAG AXLE
- ☒ WET KIT
- ☐
- ☐
- ☐
- ☐
- ☐

**THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE**

**COMMENTS: Mileage Unverified.**

EMPLOYEE'S FULL NAME (PLEASE PRINT) _____ DATE _____ EMPLOYEE'S SIGNATURE _____

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.



The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125