RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	8011058
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	1999			
MAKE:	FM GRU	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	RB 8.28i	☐ OPERATIONAL		
SN:	11877	☐ NON OPERATIONAL		
POWER:	None	☒ UNTESTABLE		
DESCRIPTION:	Crane			
SHOT / COUNT / HOUR: N/A				
NOTES / COMMENTS: Hours unverified. Wheeled unit, wheel size 11.5-15, left rear has a hole in the side wall. 51'Lx10.1'Hx15W as it sits. 154,000Lbs.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☒ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☐ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

2/15/18

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107