RTR Services Inc. BOX TRUCK CONDITION REPORT		RTR #:	8103355
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2012	MILES	283,088			VIN#:	3HAMMAAL0CL536177				
MAKE:	International	GVW:	25,999	BOX HEIGHT	13'0"	BOX LENGTH	26'	BOX WIDTH	96"		
MODEL:	4300	WHEELBASE:				COLOR: EXTERIOR:	White	INTERIOR:	Gray		
ENGINE:	Maxxforce	HP	210			KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL				ANTIFREEZE TESTED: ☒ YES ☐ NO		RATING:	-20°		
DOES MOTOR RUN?	☐ YES	☒ NO	CAN IT BE DRIVEN?	☐ YES	☒ NO	COLLISION DAMAGE?	☒ YES	☐ NO			

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☐	☐	☒	
	HOOD	☐	☒	☐	☐	One hood cable broken
	TURN SIGNALS	☐	☐	☐	☒	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☐	☒	☐	
	REAR BUMPER	☐	☐	☒	☐	
	TAIL LIGHTS	☐	☐	☐	☒	
	REAR PANEL	☐	☐	☒	☐	Rusty, bent
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☐	☒	☐	
	TOP	☐	☐	☒	☐	Top corners of box broke open
TIRES	D FRONT	☐	☒	☐	☐	% 90 SIZE: 11R 24.5
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 90 SIZE: 11R 24.5
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☒	☐	☐	% 90 SIZE: 11R 24.5
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 90 SIZE: 11R 24.5
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☐	☒	☐	Worn
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☐	☐	☒	
	BOX	☐	☐	☐	☒	Door broken cannot open

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☒	☐	☐	Check engine light on
	TRANSMISSION	☐	☐	☒	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☐	☒	☐	☐	
	BRAKES	☐	☐	☒	☐	☐	
	FRONT END	☐	☐	☒	☐	☐	
	REAR END	☐	☐	☒	☐	☐	
	BATTERY/ELECTR	☒	☐	☐	☐	☐	New batteries 11/23/2018
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☐ AIR CONDITIONER
- ☒ AIR RIDE SEAT D/P D
- ☐ AIR RIDE SUSPENSION
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☐ TRANSLUCENT ROOF
- ☐ E-TRACK LINING
- ☐ BOX DOME LIGHT
- ☐ SIDE DOOR
- FUEL TANKS
  - ☒ SINGLE GAL 70
  - ☐ DUAL GAL _____
- ☐ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☒ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S
- SUSPENSION
  - ☐ AIR
  - ☐ SPRING
  - ☐ PAD
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX _____
- ☐ LIFT/TAG AXLE
- ☐ RAMP
- ☒ LIFT GATE
- ☐
- ☐
- ☐
- ☐
- ☐

COMMENTS: Rust on rear of truck & liftgate. Will not start. Mileage unverified.

11/6/2018

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107